

SPECIAL OPEN SESSION

SPECIAL OPEN MEETING OF THE BOARD OF DIRECTORS OF THE THIRD LAGUNA HILLS MUTUAL A CALIFORNIA NON-PROFIT MUTUAL BENEFIT CORPORATION

Thursday, May 23, 2024 - 9:30 a.m. 24351 El Toro Road, Laguna Woods, California Board Room/Virtual Meeting

Laguna Woods Village owners/residents are welcome to participate in all open meetings in-person and virtually. To submit comments or questions virtually for meetings, please use one of the following options:

- 1. Join the meeting via Zoom by clicking this link: <u>https://us06web.zoom.us/j/92081839160</u> or by calling 1-669-900-6833, Webinar ID: 92081839160.
- 2. Via email to <u>meeting@vmsinc.org</u> any time before the meeting is scheduled to begin or during the meeting. Please use the name of the meeting in the subject line of the email. Name and unit number must be included.

NOTICE OF MEETING AND AGENDA

This Meeting May Be Recorded

The purpose of this meeting is to review the budget for the Third Laguna Hills Mutual in accordance with *Civil Code* §4930 and was hereby noticed in accordance with *Civil Code* §4920

- 1. Call meeting to order / Establish Quorum Treasurer Andy Ginocchio
- 2. State Purpose of Meeting Treasurer Ginocchio
- 3. Approval of Agenda
- 4. Chair Remarks
- 5. Open Forum (Three Minutes per Speaker)
- 6. Responses to Open Forum Speakers
- 7. Review of the Proposed 2025 Business Plan Version 1 Maintenance and General Services Review
- 8. Adjournment



STAFF REPORT

DATE: May 23, 2024 FOR: Board of Directors SUBJECT: Proposed 2025 Business Plan – Version 1 Maintenance and General Services Review

RECOMMENDATION

Staff recommends that Board review the proposed 2025 service levels and provide direction for change or revision.

DISCUSSION

On May 23, 2024 the Board will meet to review all components of the proposed operating and reserve expenditure budgets for Maintenance & Construction and General Services. A brief narrative for each of the budgetary line items is listed in order of appearance and changes resulting from the meeting will be incorporated into future versions of the 2025 business plan. Managers responsible for the programs will be in attendance and available to answer questions at the meeting.

FINANCIAL ANALYSIS

In this version of the 2025 Business Plan, the operating portion of the M&C budget totals \$2,551,990 for maintenance services such as, plumbing, carpentry and pest control (Attachment 1). This proposal reflects an increase of \$348,015 or 16% when compared to the current year budget. These programs are funded from the Operating Fund and will require an increase in the assessment of \$4.75 per manor per month as presented.

In this version of the 2025 Business Plan, the operating portion of the General Services budget totals \$1,577,145 for general maintenance services such as, janitorial, concrete services, and gutter cleaning (Attachment 1). This proposal reflects an increase of \$3,193 or <1% when compared to the current year budget. These programs are funded from the Operating Fund and will require an increase in the assessment of \$0.04 per manor per month as presented.

The planned reserve expenditures for M&C totals \$11,982,357, an increase of \$1,361,539 or 13% (Attachment 2). Reserve components cover large repair, remediation, or replacement programs such as painting, dry rot, and paving. An increase in planned reserve expenditures may impact the assessment. All reserve components will be evaluated through a 30-year reserves plan and presented for Board consideration at the July 15, 2024 business planning meeting.

Third Laguna Hills Mutual **Proposed 2025 Business Plan – Version 1 Maintenance and General Services Review** May 23, 2024 Page 2

The planned reserve expenditures for General Services totals \$125,692, an increase of \$4,781 or 4% (Attachment 2). Reserve components cover programs such as prior to paint, paving, and exterior walls. An increase in planned reserve expenditures may impact the assessment. All reserve components will be evaluated through a 30-year reserves plan and presented for Board consideration at the July 15, 2024 business planning meeting.

The M&C planned expenditures from the Disaster Fund totals \$1,243,384, an increase of \$193,104 or 18% (Attachment 3).

An additional line item is included for Garden Villa Rec Rooms, proposed with a budget of \$128,605 for 2025, an increase of \$31,103 or 32% when compared to current year budget. This item is a surcharge to those units that are located within a Garden Villa style building.

Prepared By:	Jose Campos, Assistant Director of Financial Services
Reviewed By:	Steve Hormuth, Director of Financial Services

Attachments

ATTACHMENT 1 – Maintenance and General Services Expenditures by Program with Narratives – Operating Fund

ATTACHMENT 2 – Maintenance and General Services Expenditures by Program with Narratives – Reserve Fund

ATTACHMENT 3 – Maintenance Services Expenditures by Program with Narratives – Disaster and Garden Villa Fund

THIRD LAGUNA HILLS MUTUAL 2025 PLAN PROGRAMS REPORT

		2021	2022	2023	2024	2025	14505		OUTSIDE		Assessm Increase/(De	
	DESCRIPTION	ACTUALS	ACTUALS	ACTUALS	BUDGET	BUDGET	LABOR	MATERIALS	SERVICES	HOURS	\$	%
			OP	ERATING FUND	- MAINTENANO	E & CONSTRU	CTION					
	PLUMBING SERVICE	\$716,714	\$691,819	\$782,057	\$786,186	\$844,762	\$662,762	\$62,000	\$120,000	8,500	\$58,576	7
Ļ.	A791000000 General Plumbing Service	598,524	583,457	615,852	605,852	649,897	467,897	62,000	120,000	6,000	44,045	7
ŧ.	A791000000 General Plumbing Service	194	2,897	1,260	0	0	0	0	0	0	0	0
	A791007919 Leak Investigation	117,996	105,465	164,945	180,334	194,865	194,865	0	0	2,500	14,531	8
	CARPENTRY SERVICE	\$424,622	\$535,988	\$625,276	\$586,661	\$592,461	\$498,961	\$75,750	\$17,750	7,050	\$5,800	1
2	A320010000 Carpentry Service DMO Only	415,221	456,551	536,038	558,237	572,305	502,305	70,000	0	6,175	14,068	3
)	A320010000 Carpentry Service DMO Only	0	0	0	15,750	15,750	0	0	15,750	0	0	C
2	A965900000 Chargeable Service-OPERATING FUND	0	19,540	23,285	0	0	(500)	500	0	100	0	(
2	A320900000 Carpentry Service-Chargeable-OPERATING FUND	0	50,391	57,532	0	0	(5,000)	5,000	0	750	0	0
)	A310120000 Lead Abatement - Carpentry Services	0	0	0	2,625	2,000	0	0	2,000	0	(625)	(24
2	A964050000 Support Scaffolding	6,008	5,698	4,680	4,988	0	0	0	0	0	(4,988)	(100
·	A917229910 Repair Elevator and Mailroom Tile Floors	513	0	0	0	0	0	0	0	0	0	0
·	A917169916 Vinyl Floor Repairs	2,880	3,808	3,742	5,061	2,406	2,156	250	0	25	(2,655)	(52
	PEST CONTROL	\$366,892	\$180,881	\$335,580	\$377,116	\$655,000	\$0	\$0	\$655,000	0	\$277,884	74
)	A310080000 Fumigation- Motel Bills	45,528	7,758	49,676	51,616	90,000	0	0	90,000	0	38,384	74
)	A320050000 Fumigation- Pest Control	32,500	60,538	50,760	47,250	70,000	0	0	70,000	0	22,750	48
)	A320060000 Fumigation- Inspections	0	0	0	46,800	50,000	0	0	50,000	0	3,200	
)	A320080000 Fumigation- Tenting	253,368	104,017	214,540	194,700	400,000	0	0	400,000	0	205,300	105
)	A31008OS01 Fumigation - Landscaping	35,496	8,568	20,604	36,750	45,000	0	0	45,000	0	8,250	22
	FIRE PROTECTION	\$88,415	\$142,282	\$78,254	\$151,185	\$154,868	\$3,521	\$2,197	\$149,150	60	\$3,683	2
)	A400090000 Fire Alarm Inspections for all multi-story buildings	(240)	0	0	0	0	0	0	0	0	0	(
Ł.	A400090000 Fire Alarm Inspections for all multi-story buildings	45,192	43,759	29,072	58,500	58,500	0	0	58,500	0	0	(
£	A330000000 Fire Extinguisher Service	30,178	28,338	20,034	30,650	30,650	0	0	30,650	0	0	(
£	A330030000 Sprinkler System Service	2,349	2,835	0	20,000	20,000	0	0	20,000	0	0	(
£	A330040000 Standpipe Testing	0	41,080	0	8,000	8,000	0	0	8,000	0	0	(
)	A31001OS78 Dryer Vent Cleaning	5,418	19,773	21,403	26,250	30,000	0	0	30,000	0	3,750	14
)	A330110000 Chimney Cleaning	1,161	784	1,390	2,100	2,000	0	0	2,000	0	(100)	(5
3	A380091000 Smoke Detector Repair/Replace	4,356	5,713	6,356	5,685	5,718	3,521	2,197	0	60	33	
	ELECTRICAL SERVICE	\$126,478	\$16,030	\$31,511	\$104,443	\$99,030	\$67,795	\$23,000	\$8,235	1,687	(\$5,414)	(
3	A300060000 Electrical Service DMO	126,478	117,107	120,162	104,443	99,030	77,095	13,700	8,235	1,325	(5,414)	(
3	A340900000 Resident Maintenance Fees	0	16,030	31,511	0	. 0	(9,300)	9,300	0	362	0 Ó	Č.
	APPLIANCE REPAIRS	\$84,181	\$87,868	\$73,374	\$115,384	\$118,869	\$104,569	\$14,300	\$0	1,383	\$3.486	
	A300050000 Miscellaneous Appliance Repairs	0	57	0	0	0	0	0	0	0	0	
	A300100000 Emergency Service Access	1,840	2,168	1,846	2,404	2,517	2,517	0	0	33	113	
	A350001401 Washing Machine Repairs	71,128	75,349	64,716	88.057	90,701	79,401	11.300	0	1.050	2.644	
	A350001501 Dryer Repairs	11,212	10,294	6,811	24,922	25,652	22,652	3,000	0	300	729	
	MISCELLANEOUS REPAIRS BY OUTSIDE SERVICES	\$39,560	\$11.079	\$9.067	\$30,000	\$30,000	\$0	\$0	\$30.000	0	\$0	
)	A310010000 Misc. Repairs by Outside Services	27,531	10,608	9,067	30,000	30,000	0	0	30,000	0	0	(
9	B121327000 Caport 338	3,128	.0,000	0	0	0	0	Ő	0	0	õ	
	Miscellaneous	8,901	472	ŏ	ő	_0	Ő	Ő	0	0	ň	
·	SOLAR MAINTENANCE	\$14.348	\$23,539	\$50,516	\$36,000	\$37,000	\$0	\$0	\$37.000	ñ	\$1.000	
)	A920201707 Third Solar O&M	14,348	23,539	50,516	36,000	37,000	0	0	37,000	0	1,000	
	STREET LIGHT MAINTENANCE	\$0	\$0	\$12,946	\$17,000	\$20.000	so	\$0	\$20,000	ñ	\$3.000	1
)	A900220000 Street Light O&M	0	0	12,946	17,000	20,000	0	40	20,000	0	3,000	1
	TOTAL	\$1,891,197	\$1,689,487	\$1,998,581	\$2.203.975	\$2.551.990	\$1,337,608	\$177.247	\$1,037,135	18.680	\$348,015	16

Line 9 was moved from Reserves to Operating in 2023.

THIRD LAGUNA HILLS MUTUAL 2025 PLAN PROGRAMS REPORT

		2021	2022	2023	2024	2025			OUTSIDE		Assessm Increase/(Dec	
	DESCRIPTION	ACTUALS	ACTUALS	ACTUALS	BUDGET	BUDGET	LABOR	MATERIALS	SERVICES	HOURS	\$	%
				OPERATING	FUND - GENE	RAL SERVICES						
10	JANITORIAL SERVICE	\$979,609	\$969,445	\$899,490	\$904,120	\$892,757	\$866,757	\$26,000	\$0	19,204	(\$11,362)	(1%
935	A961001014 Bulky Item Pickup	67,290	66,983	26,509	0	0	0	0	0	0	0	0%
935	A961011001 Janitorial Svcs - Three-Story Buildings	783,007	771,456	712,542	777,929	768,992	756,992	12,000	0	16,770	(8,937)	(1%
35	A961011002 Janitorial Svcs - Free Standing Laundries	62,023	66,510	56,790	73,457	72,763	58,763	14,000	0	1,303	(694)	(1%
35	A961011004 Janitorial Svcs - Miscellaneous	21,638	19,101	48,495	14,724	14,552	14,552	0	0	323	(172)	(1%
35	A961011005 Janitorial Svcs - Breezeways/Common Areas	19,263	19,101	30,906	24,828	23,422	23,422	0	0	520	(1,406)	(6%
935	A961011006 Janitorial Svcs - Car Port Cleaning	26,388	26,296	24,248	13,181	13,028	13,028	0	0	288	(154)	(1%
11	CONCRETE SERVICE	\$403,056	\$317,129	\$386,373	\$336,286	\$352,348	\$311,348	\$41,000	\$0	4,169	\$16,062	5%
36	A962050000 Concrete Repair/Replacement	363,393	277,998	342,934	323,259	338,729	298,729	40,000	0	4,000	15,470	5%
36	A962070000 Sweeping	0	0	0	0	0	0	0	0	0	0	0%
36	A962140000 Masonry	10,994	10,870	12,111	0	0	0	0	0	0	0	0%
36	A962150000 Chain Link Fence Repair/Replacement	557	580	646	0	0	0	0	0	0	0	0%
36	A962160000 Graffiti Removal	557	580	646	349	361	361	0	0	5	12	3%
36	A962190000 Sweeping/Scrubbing Garages	27,555	27,102	30,036	12,679	13,259	12,259	1,000	0	164	580	5%
12	GUTTER CLEANING	\$73,777	\$144,267	\$135,528	\$207,597	\$200,011	\$134,311	\$0	\$65,700	1,800	(\$7,586)	(4%
36	A962100000 Gutter Cleaning	73,777	144,267	135,528	207,597	200,011	134,311	0	65,700	1,800	(7,586)	(4%
13	WELDING	\$118,439	\$106,756	\$98,365	\$107,821	\$113,099	\$101,499	\$1,600	\$10,000	1,360	\$5,279	5%
36	A962350000 Dry Rot Balcony Welding Repairs	0	0	646	797	821	721	100	0	10	24	3%
36	A962330000 Stair Tread Replacements	16,778	16,232	18,086	3,486	3,786	3,786	0	0	50	300	9%
36	A962120000 Welding	93,226	82,753	79,632	93,537	98,492	96,992	1,500	0	1,300	4,955	5%
36	A310180000 Lead Abatement - Welding	8,435	7,770	0	10,000	10,000	0	0	10,000	0	0	0%
14	TRAFFIC CONTROL	\$20,648	\$18,999	\$21,334	\$18,129	\$18,930	\$18,930	\$0	\$0	255	\$801	4%
36	A962020000 Traffic Control	4,532	4,348	5,024	5,752	5,949	5,949	0	0	80	197	3%
36	A962360000 Traffic Paint Program	8,507	8,116	9,043	7,147	7,392	7,392	0	0	100	245	3%
936	A962500000 Sign Replacement	7,608	6,535	7,267	5,229	5,589	5,589	0	0	75	359	7%
	TOTAL	\$1,595,528	\$1,556,596	\$1,541,090	\$1,573,953	\$1,577,145	\$1,432,845	\$68,600	\$75,700	26,788	\$3,193	0%

THIRD LAGUNA HILLS MUTUAL 2025 OPERATING EXPENDITURES MAINTENANCE AND CONSTRUCTION

The General Maintenance Operating section covers the inspection, maintenance and repair of structures including, but not limited to, manor interiors, building exteriors, carports, laundries, balconies, railings and stairs. Primarily these maintenance items are in response to resident service requests, although many items are planned program work.

1) Plumbing Service

\$844,762

This item provides funding for the variety of plumbing services related to plumbing components that are the responsibility of the Mutual. The main categories of service include addressing various types of stoppages, leak investigation and remedial work related to plumbing leaks (in-wall, under-slab, etc.). Since 2015, plumbing technicians also perform drywall cuts to expedite repairs to in-wall leaks and pipe re-routes. The technicians are certified to handle the removal/abatement of drywall. This will allow, in most cases, a single visit by one department to a manor for the cutout and repair process. Service levels are based on historical averages of hours, materials, and outside services.

Underground leaks are addressed by certified contractors due to CAL OSHA shoring requirements and asbestos cement pipe (Transite) repair and abatement concerns. A contingency amount is included in the budget for such services.

2) Carpentry Service

\$592,461

This line item provides for response to service requests for carpentry and carpentryrelated service work on the Mutual's buildings, carports and laundry facilities. Items addressed through Carpentry Services include, but are not limited to the following:

- Exterior and entry door repair
- Repair/replace entry locks
- Door weather stripping replacement
- Board-up windows/shore up sites
- Building cracks and stucco repair
- Acoustic ceiling repair
- Laundry room window repair
- Insect screen install/repair
- Cabinet repair
- Carport structure repair

- Carport cabinet repair
- Garage door repair
- Patio gate repair
- Vinyl and tile floor repairs
- Removal of bird/animal in wall
- Drywall/texture repair
- Mailbox door and lock repair
- Support scaffolding set-up
- Wall/ceiling insulation replacement

Budgeting for this item is essential to continue maintaining the high service level expected and to complete all necessary maintenance concerns requested by residents for the services described above in a timely manner. These repairs are performed by in-house staff and outside contractors.

3) Pest Control

A licensed pest control contractor provides the Mutual with pest control services for termite eradication and bee removal services.

The budget is typically developed based on historical trends and the existence of termites as identified by the Mutual's fumigation contractor. A staff inspector and a representative of the fumigation contractor conduct inspections in response to all reported evidence of live termites and upon request at the time a manor is resold. Additionally, in 2023 the Board began funding proactive termite inspections, using a separate pest control vendor. Inspections will take place on the exterior components of 1,405 residential buildings, 295 carports, and 44 laundry buildings over a 3-year cycle. Approximately 580 buildings/structures will be inspected each year.

Based on the results of all inspections, a list of buildings requiring fumigation is compiled. Whenever possible, localized treatments of the infested areas will be performed for dry wood termites to minimize the fumigation requirements. Subterranean termites are also treated at the localized point of infestation.

The buildings listed for fumigation typically are scheduled for the following fiscal year and worked into the budget. Fumigation costs are based on a pre-determined contract value per building size.

The projected costs are budgeted in five categories, Local Pest Control Treatments; Proactive Termite Inspection Program; Fumigation - Tenting; Fumigation - Landscaping (for plant removal); and Fumigation - Lodging. Although not required by the Davis-Stirling Act, Mutual policy provides lodging for two nights while the whole structure fumigation is in process.

The lodging budget is based on the number of manors contained in each of the buildings to be fumigated and the contracted rate in place with a local hotel.

The budget for whole structure tenting is based on a weighted average of each building type with costs applied to those buildings based on a pre-determined contract value per building type.

This approach is used to determine budgetary estimates for the Business Plan, as the full list of actual buildings that will require treatment are often not known until after the preparation of a given year's Business Plan.

However, the increase in funding levels for 2025 is due to a larger than average number of buildings requiring whole structure fumigation. In 2024, 53 buildings were fumigated. The number of buildings currently on the list for fumigation in 2025 are 107. This number is expected to increase as the proactive termite inspections are conducted.

4) Fire Protection

(A) Fire Alarm System Inspections for All Multi-story Buildings

This item addresses fire alarm system inspections that take place twice a year for all 81 3-story buildings.

(B) Fire Extinguisher Service

This service, provided by an outside vendor, covers the annual inspection, maintenance and repair or replacement of the 1,300 fire extinguishers located throughout Third Laguna Hills Mutual. This service includes: (1) inspection and replacement (as needed) of various components; (2) replacement of powders and gases; (3) hydrostatic testing when required; (4) proper tagging of fire extinguishers to indicate date of service and certification; (5) replacement of irreparable or missing extinguishers and extinguishers that must be replaced in accordance with Fire Authority regulations and (6) repair of extinguisher cabinet glass and other parts.

(C) Sprinkler System Service

This item is used to address the inspection and servicing of the fire suppression sprinkler systems in the trash chutes of three-story buildings. Sprinkler system service includes certified contractor quarterly inspection of all components of the system and implementation of identified repairs. All work is per NFPA 14 and California Title 19 fire regulations. Staff included funding based on contract pricing for quarterly inspections and provisions for repairs in 2025.

(D) Standpipe Testing

This item is used to address the inspection and repair of the Fire Standpipe Systems (Class I or II standpipe systems) in each of the 53 Garden Villa style buildings. NFPA requires semi-annual inspection of these systems. Additionally, NFPA requires flow testing/certification and fire hose pressure testing/certification by a qualified contractor on a five-year schedule or when repairs or use of the system results in the need for certification.

For the 2025 Business Plan, staff included funding for the required annual inspections and a contingency for as needed system repairs determined to be necessary during the inspection process.

(E) Chimney Cleaning

This item is used for repair or replacement of spark arrestors on original chimneys.

(F) Dryer Vent Cleaning

This item is used to address the cleaning of original dryer vent ducts in both laundry facilities and manors with original dryer hookups throughout Third Laguna Hills Mutual. The dryer vents in the LH-21 buildings are cleaned every year.

5) Electrical Service

\$99,030

This item provides funding for the variety of electrical services related to electrical components that are the responsibility of the Mutual, which include the following:

•

lighting

Replace main breaker

Replace common area

Repair/replace common area

- Repair/replace common area outlets
- Service common area circuit breaker
- Repair underground wiring
- Replace conduit and wiring
- Replace damaged doorbell light

6) Appliance Repairs

\$118,869

This item addresses repairs to the Mutual's laundry appliances. The Mutual maintains 455 high-efficiency laundry room washing machines. In 2019, the Mutual installed 373 high-efficiency commercial dryers in common area laundry rooms.

Budgeting for this item is based on historical trends, but may slowly decrease in the future for a period of time, as the new Speed Queen washing machines replace the failed Maytag, Whirlpool and GE units.

7) Miscellaneous Repairs by Outside Services \$30,000

This funding is used to address items that are typically repaired by outside contractors. This item also includes funding for other repairs that that do not fit into one of the categories below.

As these items are emergent in nature, budgets are based on historical averages, trends and on planned program scopes of work.

(A) Broken Windows

Replacement of broken panes of glass in the Mutual's common area makes up the majority of this category. Also included in this item are repairs and replacements to window frames, weather stripping and hardware that are the responsibility of the Mutual.

(B) Phone Line Repairs

This item is used to address repairs associated with the Mutual's responsibility for providing one working phone line to each manor.

(C) Lead Paint Testing

In 2010, new EPA regulations went into effect requiring special procedures and handling when performing Renovation, Repair and Painting (RRP) of building components where lead-based paint is present. The presence of lead in paint must be determined before proceeding with work that qualifies under the regulations. Determination of the presence of lead paint must be performed by a Certified Lead Inspector/Risk Assessor. This budget is included to pay for the costs of lead testing performed by a Certified Lead Inspector/Risk Assessor on miscellaneous projects that will be completed by an outside service. Staff included an estimated provision for such testing and abatement.

(D) Miscellaneous

This item includes funding for other repairs that require outside services, but that do not fit into one of the above categories. A two-year average of miscellaneous costs was used as the basis for this category.

8) Solar Maintenance

\$37,000

This item provides for the Operation and Maintenance (O&M) services set forth below by an outside contractor in relation to the Third solar energy projects. The 2025 budget includes a contingency for repairs.

Daily:

- Real-time performance monitoring and alert triage
- Product warranty administration (creating/tracking/logging)
- 24/7 customer support

Annually:

- Inverter inspection, maintenance and thermal scans
- DC wiring and electrical equipment inspections, maintenance, thermal scans and performance testing (current at maximum power (IMP)& operating circuit voltage (VOC) on 100% of the strings
- Solar module inspection and thermal scans
- Array racking and component inspection and maintenance
- Inspection, cleaning and maintenance of meters and sensors
- Pyranometer calibration

- Removal of material within arrays and balance of system (BOS)
- Repairs and replacements as required
- Maintenance summary report
- 2x Annual Module cleaning/washing

9) Street Light Maintenance

\$20,000

Funding for this item was moved from Reserves to Operating for the 2023 fiscal year, to provide as needed maintenance services to the existing street light infrastructure and LED fixtures.

An outside contractor responds to reported street light outages and will perform repairs or replacements to poles and/or fixtures, as required.

THIRD LAGUNA HILLS MUTUAL 2025 OPERATING EXPENDITURES GENERAL SERVICES

This section covers the inspection, maintenance and repair of breezeways and common areas for multi-story buildings, carports, laundry rooms, concrete, rain gutters, railing and stairs, and traffic control striping and signage. Primarily, these maintenance items are in response to resident service requests, although many items staff reported and planned program work.

10) Janitorial Service

\$892,757

Service levels provided in this category include janitorial services for breezeways and common areas of multi-story buildings, free-standing laundry buildings, and miscellaneous janitorial services in Mutual common areas and car port cleanings. Budgeting for this category is based on the following established service levels:

Third Mutual	Frequency
Two-Story Buildings (Breezeways)	Upon request
Laundry Rooms	Every 3 weeks
Laundry Restrooms	1x week
Garden Villas	1x week
LH 21 Buildings	1x week
Miscellaneous Tickets	Weekly
Programs	
Carport Cleaning	3x year
Water Boiler Enclosure Cleaning	1x year
Trash Enclosure Cleaning	1x year

11) Concrete Service

\$352,348

This line item addresses pro-active and resident requests for repair or replacement of concrete slabs, walkways and driveways. Concrete repairs include crack filling and the grinding-down of walkways that have lifted. Replacement of concrete occurs when lifting exceeds the two-inch grinding capability. Replacement may also occur when water pooling exceeds ½ inch without draining, or when cracks or damage create inadequate load bearing capacity.

Concrete Repair/Replaced	258
Masonry Work	29
Concrete Grinding Completed	55
Paving Misc. Service	25

12) Gutter Cleaning

This item provides for the cleaning of building rain gutters to ensure their proper function and drainage. The majority of the work is completed during the fourth quarter of the year.

The budget includes funding for an outside service to clean the gutters of multiple- story buildings once during the fourth quarter of the year. In-house staff will clean gutters of single-story buildings throughout the year on a scheduled and as-requested basis.

Single-Story	894
Multi-Story	337
Patio Covers	1,471

13) Welding

Welding services are utilized in the repair/replacement of railings, gates, fences, and the repair/replacement of steel step rails. This item includes work completed as requested by staff and residents through service requests to Resident Services. Historical averages and trends are used to develop budgetary estimates. A contingency amount for lead testing and abatement, required due to EPA lead handling regulations, is included.

 WC 936 Streets and Sidewalks receives approximately 110 welding tickets per year for Third

14) Traffic Control

This line item addresses the installation and maintenance of devices required to facilitate traffic safety and circulation throughout the Community. This includes parking lot and street striping, red and yellow curb painting, crosswalk painting, and replacement of directional and vehicular control signage.

15-21) Landscape Services

These items will be reviewed at the Landscape budget meeting.

\$200,011

\$18,930

\$113,099

THIRD LAGUNA HILLS MUTUAL 2025 PLAN PROGRAMS REPORT

	DESCRIPTION	2021 ACTUALS	2022 ACTUALS	2023 ACTUALS	2024 BUDGET	2025 BUDGET	LABOR	MATERIALS	OUTSIDE SERVICES	HOURS	Assessm Increase/(De \$	
			RI	ESERVE FUNDS	- MAINTENANO	E & CONSTRUC	CTION					
	BUILDING NUMBERS	\$14,088	\$0	\$0	\$0	\$0	\$0	\$0	\$0	0	\$0	0%
)	A310100000 Illuminated Building Numbers	14,088	0	0	0	0	0	0	0	0	0	0%
	BUILDING STRUCTURES	\$2,091,312 243.317	\$1,809,120	\$2,403,923	\$2,300,426 500,000	\$2,486,143	\$261,518	\$103,500	\$2,121,125 700,000	3,210	\$185,717	8% 40%
)	A959100000 Building Structures (Maintenance Ops) A950210000 Carport Panel Replacements	11,410	156,823 4,456	322,379 6,283	10,233	700,000 4.273	1,773	2,500	700,000	0 20	200,000 (5,960)	(58%)
	A959120000 Building Structures (Carpentry)	220,953	198,906	55,808	86,169	4,273	52,757	50,000	0	650	16,588	19%
)	A959200000 Building Structure Dry Rot	578.350	272.172	181.860	210.000	210,000	52,757	0,000	210.000	0.00	10,500	0%
,	A950050000 Building Structure Replacement (Third)	198,017	329,963	455.062	350,000	150,000	0	0	150,000	0	(200,000)	(57%)
)	A950011000 Balcony Inspection	0	0_0	74,328	92,495	0	Ő	Ő	0	Ő	(92,495)	(100%)
)	A959120000 Building Structures (Carpentry)	26,527	22,349	34,809	30,000	0	0	0	0	0	(30,000)	(100%)
	A959120000 Building Structures (Carpentry)	4,716	6,455	3,389	5,710	4,494	3,494	1,000	0	40	(1,216)	(21%)
2	A959120000 Building Structures (Carpentry)	1,202	10,240	0	0	0	0	0	0	0	Ŭ O	0%
)	A920201705 PARAPET WALL REMOVAL - THIRD	253,820	0	0	150,000	168,000	0	0	168,000	0	18,000	12%
)	A950220000 Foundations	19,142	23,575	35,872	25,000	25,000	0	0	25,000	0	0	0%
)	A310130000 Lead Abatement – Dry Rot	1,450	540	0	5,250	5,500	0	0	5,500	0	250	5%
2	A320100000 Dry Rot Repair- Tickets	132,533	157,813	170,867	167,944	253,493	203,493	50,000	0	2,500	85,550	51%
)	A320100000 Dry Rot Repair- Tickets	0	0	0	2,625	2,625	0	0	2,625	0	0	0%
)	A991020000 Moisture Intrusion - Rain Leaks Reserves	45,284	224,620	522,891	200,000	200,000	0	0	200,000	0	0	0%
)	A992020000 Moisture Intrusion - Plumbing Leaks Reserves	242,588	338,410	416,954	350,000	330,000	0	0	330,000	0	(20,000)	(6%)
	A993020000 Moisture Intrusion - Plumbing Stoppages Reserves	40,199	82,189	71,075	65,000	65,000	0	0	65,000	0	0	0%
	A994020000 Moisture Intrusion - Other Reserves	71,804	(19,392)	52,346	50,000	65,000	0	0	65,000	0	15,000	30%
)	A962102000 Dry Rot Roof Repair PTP	•	0	U	0	200,000	0	0	200,000	0	200,000	100%
	ELECTRICAL SYSTEMS	\$16,588 16,588	\$0 0	\$0 0	\$30,000	\$62,000 30,000	\$0	\$0 0	\$62,000	0	\$32,000	107% 0%
3	A950240000 Electrical Panel Maintenance A950020000 Electrical System Replacement	10,566	0	0	30,000	32,000	0	0	30,000 32,000	0	32,000	100%
	EXTERIOR LIGHTING	\$24,840	\$14,473	\$12,062	\$12,500	\$12,925	\$75	\$0	\$12,850	1	\$425	3%
)	A910800000 Exterior Lighting	7,853	φ1+,+/3 0	φ12,002 0	φ12,500 0	\$12,525	\$75 0	φ υ 0	φ12,030 Ω	0	φ 4 25	0%
	A910800000 Exterior Lighting	1,000	1,850	12,850	12,500	12,925	75	Ő	12,850	1	425	0,0
	A910800000 Exterior Lighting	16.987	12.623	(788)	.2,000	0	.0	0	.2,000	0	.20	
	FENCING	\$73.009	\$62.837	\$75.237	\$79.602	\$70.757	\$52.757	\$18.000	\$0	650	(\$8.844)	(11%)
	A950200000 Split Rail Fence Replacements	73,009	62,837	75,237	79,602	70,757	52,757	18,000	0	650	(8,844)	(11%)
	GARDEN VILLA LOBBY	\$111,882	\$1,418	\$0	\$0	\$0	\$0	\$0	\$0	0	\$0	0%
)	A950260000 Garden Villa Lobby Flooring	111,882	1,418	0	0	0	0	0	0	0	0	0%
	GARDEN VILLA MAILROOM	\$300	\$285	\$293	\$562	\$577	\$327	\$250	\$0	5	\$15	3%
2	A950280000 Garden Villa Mailroom - Paint	300	285	293	562	577	327	250	0	5	15	3%
	GARDEN VILLA REC ROOM	\$7,859	\$2,759	\$8,472	\$65,393	\$68,109	\$1,109	\$2,000	\$65,000	15	\$2,716	4%
-	A790127941 Rec Room Water Heater Replacement	5,788	907	2,136	3,004	3,109	1,109	2,000	0	15	105	3%
5	A790007941 Manor Water Heater Replacement	0	17	47	0	0	0	0	0	0	0	0%
	A31001OS32 Rec Room Window Replacement	0	0	0	60,000	60,000	0	0	60,000	0	0	
	A790007941 Manor Water Heater Replacement	1,182	1,835	319	0	0	0	0	0	0	0	0%
)	A31009OS91 Rec Room Heat Pump Replacement	888	0	5,971	2,389	5,000	0	0	5,000	0	2,611	109%
	GUTTERS	(\$15,844)	\$29,973	\$67,264	\$126,486	\$203,575	\$81,575	\$12,000	\$110,000	1,000	\$77,089	61%
	A95000000 Gutter Replacement	(44,280)	0	5,177	60,000	60,000	0	0	60,000	0	0	0%
	A95000000 Gutter Replacement A962103000 Gutter Screen Installation	28,436	29,973 0	62,087 0	66,486	93,575 50.000	81,575	12,000	50.000	1,000	27,089 50.000	41% 100%
	MAILBOXES	\$37,175	\$2,743	\$11,811	\$27,582	\$0,000 \$27,640	\$12,390	\$15,250	50,000 \$0	160	50,000 \$58	0%
2	A950180000 LH 21 Mailbox Replacements	37,160	2,743	10,349	25,774	26,084	11,084	15,000	φ υ Ο	136	310	1%
,	A950180000 LH 21 Mailbox Replacements	15	2,743	1.463	1.809	1,556	1.306	250	0	24	(252)	(14%)
-	PAINT PROGRAM	\$1,527,920	\$1,413,218	\$1,445,812	\$1,613,075	\$1,757,800	\$1,506,050	\$224.000	\$27,750	25,900	\$144,725	9%
2	A971000000 Exterior Paint Program	1,233,999	1,094,433	1,146,112	1,260,747	1,352,771	1,162,771	190,000	<i>\$21,15</i> 0	20,000	92,025	5% 7%
	A971010000 Deck Topcoat Paint Follow-Up	51,735	32.630	43,087	42.297	85,897	69,897	16,000	ů 0	1,200	43,600	103%
	A971020000 Building Signs	0	11,827	9,126	52,500	20,000	0	0	20,000	0	(32,500)	(62%)
	A963006502 Exterior Touch-up	167,784	201,509	172,388	173,353	218,485	203,485	15,000	20,000	3,500	45,132	26%
	A310170000 Lead Abatement Touch-up	0	0	0	2,625	2,500	0	0	2,500	0	(125)	(5%)
	A963010000 Interior Touch-up Mutual	74,402	70,419	70,643	76,304	72,897	69,897	3,000	2,000	1,200	(3,407)	(4%)
	A971030000 Lead Testing and Abatement - Paint Program	0	2,400	4,455	5,250	5.250	,	0	5.250	0	(0,,	0%

THIRD LAGUNA HILLS MUTUAL 2025 PLAN PROGRAMS REPORT

											Assessm	
		2021	2022	2023	2024	2025			OUTSIDE		Increase/(Dec	crease)
	DESCRIPTION	ACTUALS	ACTUALS	ACTUALS	BUDGET	BUDGET	LABOR	MATERIALS	SERVICES	HOURS	\$	%
33	PRIOR TO PAINT	\$1.024.160	\$1.042.713	\$1.161.592	\$1,222,353	\$1,437,585	\$1.192.585	\$180.000	\$65.000	14.650	\$215.232	18%
912	A981000000 Dry Rot Repairs - Prior-to-Paint	\$1,024,160 524,688	573,036	\$1,161,592 658,886	\$1,222,353 684.099	\$1,437,585 669,692	\$1,192,585 569.692	100.000	\$65,000	7,000	\$215,232 (14,407)	(2%)
912	A981000000 Dry Rot Repairs - Phot-to-Paint A981010000 Decking Repairs (Prior to Paint)	77,504	85,958	126,879	104,882	274,280	244,280	30,000	0	3,000	169,398	(2%) 162%
910	A981020000 Lead Testing and Abatement - Prior-to-Paint	52.546	8,312	54.942	57,750	65,000	244,200	30,000	65,000	3,000	7,250	13%
912	A965170000 Decking - Breezeway Common Area	114,089	116,992	126.041	142,983	180,706	162,706	18,000	05,000	2,000	37.723	26%
912	A965186702 Decking - Garden Villa Breezeway Program	146,352	153,235	182,951	220,465	233,493	203,493	30,000	0	2,500	13,029	6%
912	A965326703 Decking - Balcony Repairs	8.637	10.306	11.893	12.174	14.414	12.414	2,000	0	2,300	2.240	18%
912	A965330000 Decking- Balconies 5 Yr Topcoat Prgm	99,436	94.874	11,095	12,174	14,414	12,414	2,000	0	150	2,240	0%
912	A981000000 - Dry Rot Repairs - Prior-to-Paint	99,430	94,074	0	0	0	0	0	0	0	0	0%
	PAVING/CONCRETE		\$423,955	•	• • •	\$801,915	0	•	\$801,915	0	¢270.004	86%
34 920	A920201703 Parkway Concrete Replacements	\$618,985 106,831	\$4∠3,955 0	\$429,521	\$431,851 60,000	\$801,915 140.000	\$0	\$0	140,000	U	\$370,064 80.000	133%
920 920	A920201703 Parkway Concrete Replacements A920180000 Golf Cart Parking and Striping	7.925	0	0	60,000 0	140,000	0	0	140,000	0	80,000	0%
	A920180000 Golf Carl Parking and Striping A910940000 Major Asphalt Repairs	458.273	•	384,882		606.000	0	0	0	0	•	91%
920			377,898		317,975		0	•	606,000	0	288,025	91% 4%
920	A962010000 Seal Coat	45,956	46,057	44,639	53,876	55,915	0	0	55,915	0	2,039	
35	ROOFS	\$1,341,440	\$1,403,246	\$1,477,360	\$1,684,823	\$1,940,618	\$0	\$0	\$1,940,618	U	\$255,795	15%
920	A910860000 BUR Replacement - PVC Cool Roof	1,066,482	1,087,948	1,093,528	1,200,000	1,388,375	0	0	1,388,375	0	188,375	16%
920	A910040000 Preventive Roof Maintenance	66,585	76,182	74,077	46,845	34,470	0	0	34,470	0	(12,375)	(26%)
920	A910010000 Roof Repairs- Emergency	99,239	122,969	133,992	130,000	202,445	0	0	202,445	0	72,445	56%
920	A910865000 OS Roof Replacement - Lightweight Roofs	109,133	116,148	117,816	250,000	257,350	0	0	257,350	0	7,350	3%
920	A962101000 Flat Roof Debris Cleanup	0	0	57,947	57,978	57,978	0	0	57,978	0	0	0%
36	EXTERIOR WALLS	\$29,280	\$29,994	\$0	\$32,400	\$0	\$0	\$0	\$0	0	(\$32,400)	(100%)
920	A910855000 Perimeter Wall Shepherds Crook	29,280	29,994	0	32,400	0	0	0	0	0	(32,400)	(100%)
37	WASTE LINE REMEDIATION	\$530,595	\$617,558	\$935,789	\$1,500,000	\$1,500,000	\$0	\$0	\$1,500,000	0	\$0	0%
904	A370150000 Waste Line Replacement	530,595	617,558	935,789	1,500,000	1,500,000	0	0	1,500,000	0	0	0%
38	WATER LINES - COPPER PIPE REMEDIATION	\$367,397	\$196,116	\$196,116	\$1,000,000	\$1,000,000	\$0	\$0	\$1,000,000	0	\$0	0%
904	A370140000 Copper Piping Replacement	0	0	0	1,000,000	1,000,000	0	0	1,000,000	0	0	0%
920	A370140000 Copper Piping Replacement	367,397	196,116	196,116	0	0	0	0	0	0	0	0%
39	PLUMBING REPLACEMENT	\$0	\$0	\$0	\$200,000	\$200,000	\$0	\$0	\$200,000	0	\$0	0%
914	A794000000 General Plumbing Replacement	0	0	0	200,000	200,000	0	0	200,000	0	0	0%
40	ELEVATORS	\$151,170	\$89,872	\$98,680	\$125,000	\$205,800	\$0	\$0	\$205,800	0	\$80,800	65%
920	A910930000 Elevator Replacement	151,170	89,872	98,680	125,000	205,800	0	0	205,800	0	80,800	65%
41	LAUNDRY COUNTERTOP/FLOOR	\$40,498	\$14,977	\$13,411	\$59,173	\$42,414	\$6,914	\$5,500	\$30,000	80	(\$16,758)	(28%)
917	A917239923 Laundry Room Floors - 3 Story Buildings	9,511	8,137	10,682	17,710	4,812	4,312	500	0	50	(12,898)	(73%)
910	A31009OS92 Abatement for Flooring Replacement	25,750	0	0	31,563	30,000	0	0	30,000	0	(1,563)	(5%)
917	A917409940 Countertops - Laundry - Third	5,237	6,840	2,730	9,900	7,602	2,602	5,000	0	30	(2,298)	(23%)
42	LAUNDRY APPLIANCES	\$60,836	\$92,085	\$170,745	\$109,593	\$164,499	\$29,904	\$131,595	\$3,000	389	\$54,907	50%
914	A790017941 Laundry Water Heater Replacement	14,909	16,178	20,576	30,389	30,305	13,305	17,000	0	170	(84)	(0%)
914	A790107941 Water Heater Permits	0	0	0	2,806	3,000	0	0	3,000	0	194	7%
911	A944101506 Laundry Drver Replacement	0	15,047	40.606	14,407	14,554	4,554	10,000	0	60	147	1%
911	A944111406 Laundry Washing Machine Replacement	45.926	60,860	109,563	61,990	116.640	12.045	104,595	0	159	54.650	88%
911	J318060000 Coin-Operated Dryers and Laundry Pedestals -OS	0	0	1.817	0.,000	0	,,,,,0,0	0	0	0	0	0%
	TOTAL	\$8.053.489	\$7.247.341	\$8,508,089	\$10,620,819	\$11,982,357	\$3,145,204	\$692,095	\$8,145,058	46,060	\$1,361,539	13%

Line 24 funding is included in the Paint Program.

RESERVE FUNDS - GENERAL SERVICES

43	PRIOR TO PAINT	\$10,437	\$10,869	\$12,112	\$14,418	\$15,263	\$14,963	\$300	\$0	200	\$845	6%
936	A981030000 PRIOR TO PAINT/DRY ROT BALCONY REP	10,437	10,869	12,112	14,418	15,263	14,963	300	0	200	846	6%
44	PAVING/CONCRETE	\$68,284	\$69,114	\$64,678	\$82,343	\$86,279	\$82,029	\$4,250	\$0	1,100	\$3,936	5%
936	A962000000 Gen. Maintenance & Street Repairs	8,350	8,136	9,043	10,783	11,328	11,178	150	0	150	544	5%
936	A962040000 Asphalt Repairs	29,478	39,384	31,574	46,532	48,710	44,710	4,000	0	600	2,178	5%
936	A962090000 Main Line Repair	5,567	5,362	5,975	7,247	7,492	7,392	100	0	100	245	3%
936	A962070000 Sweeping	11,112	2,754	3,068	0	0	0	0	0	0	0	0%
936	A962700000 Crack Filling	13,778	13,479	15,018	17,780	18,749	18,749	0	0	250	969	5%
45	EXTERIOR WALLS	\$5,600	\$0	\$0	\$24,150	\$24,150	\$0	\$0	\$24,150	0	\$0	0%
936	A910840000 Common Wall Replacement	0	0	0	10,000	10,000	0	0	10,000	0	0	0%
936	A910850000 Perimeter Wall Replacement	5,600	0	0	14,150	14,150	0	0	14,150	0	0	0%
	TOTAL	\$84,321	\$79,983	\$76,791	\$120,911	\$125,692	\$96,992	\$4,550	\$24,150	1,300	\$4,781	4%

THIRD LAGUNA HILLS MUTUAL 2025 RESERVE EXPENDITURES MAINTENANCE AND CONSTRUCTION

This section covers the inspection, maintenance and repair of structures including, but not limited to, manor interiors, building exteriors, carports, laundries, balconies, railings and stairs. Primarily these maintenance items are in response to resident service requests, although many items are planned program work.

22) Building Numbers

Funding for building address sign replacement was moved to the Paint Program budget as staff replaces building, carport and laundry room signs during the annual exterior paint program.

23) Building Structures

\$2,486,143

\$0

(A) Building Structures (Maint. Ops., Carpentry & Carport Panel Replacements)

This reserve component is designed to address building structures that are exhibiting deterioration. Staff will eradicate dry rot through a systematic and proactive approach utilizing an aggressive inspection process designed to address all buildings in Third including both architectural and structural components through outside services and in-house staff. This includes but is not limited to balcony replacements, wood balcony railing replacements, ramp replacements, walkway replacements, trellis structure replacements, beam replacements, window replacements, garage door replacements, carport panel replacements, Garden Villa Recreation Room kitchen and restroom flooring replacements, asbestos and lead abatement and testing, associated engineering cost and City building permit application and inspection fees. Replacements are qualified and generated on both a reactive and a proactive basis.

Funding increased in 2025 to address dry rot found on patio walls, balcony decks and other wood components, during the prior to paint program, using outside services.

(B) Building Structures Replacements

This reserve component is designed to address building structures that are exhibiting deterioration and will be utilized on a contingency basis. It is assumed that full replacement of this component would never be required. The unit cost is a contingency estimate for a typical building structure repair.

(C) Building Structures Dry Rot

This reserve component is dedicated to eradicating dry rot through a systematic and proactive approach utilizing an aggressive inspection process. This process is designed to address all building types within the Mutual including architectural and structural components.

(D) Parapet Wall Removals

This reserve component is to address moisture intrusion problems on the Villa Paraisa and Casa Grande style buildings by removing and replacing the parapet wall design with a sloped roof.

Three buildings were completed in 2024. As of 2025, there are 11 buildings that still require parapet wall removal. Replacements will be scheduled to occur each year, over the next 4 years.

Funding allows for parapet wall removal at three buildings in 2025.

(E) Foundations

This reserve component is dedicated to foundation repairs most often due to soil erosion and settlement. Although the unit cost will vary, it is a contingency estimate for typical foundation repairs.

As part of the 2025 fiscal budget, staff will proactively assess buildings for drainage deficiencies that could lead to building settlement and will implement the necessary repairs.

(F) Building Rehab/Dry Rot

This reserve component is designed to address building structures that are exhibiting deterioration and to eradicate dry rot identified by Members through service requests or during the course of other maintenance activities in Third to include minor replacement of wood members, such as fascia boards, shear panel repair, wood stud replacement, stucco repair, T-111/Hardi siding replacement, rafter tail replacements, exterior crown molding replacement, and red wood siding/trim replacement.

(G) Balcony Inspections

State law mandates that a statistically significant sample of all of the Mutual's exterior elevated elements is to be inspected every 9 years. VMS contracts with a licensed structural engineer or architect to inspect a percentage of the Mutual's exterior elevated elements, for which the Mutual has maintenance or repair responsibility. A report is generated from the inspections and shall include detailed information on the condition of each inspected element; expected future performance; remaining useful life; and any repair or replacement recommendations. The inspections were completed by December 31, 2024.

Inspections will be split over a two-year period, in years 8 and 9. Inspections will resume in 2032 and 2033.

(H) Damage Restoration

This reserve component is for reconstruction of mutual-controlled property in manors and buildings resulting from rain leaks, plumbing leaks, plumbing stoppages, miscellaneous moisture intrusion events, fires and other disasters.

Damage to Mutual property exceeding \$100K is submitted to the Mutual's insurance company.

Funding increased in 2025 based on an average of the actual expenditures from the last three years.

24) Electrical Systems

\$62,000

(A) Electrical Systems – Panel Replacements

This reserve component is funded to address electrical panel maintenance and includes contingency funding for panel failures and the replacement of electrical components, as necessary.

(B) Electrical Systems – Alternate Heat Source (Heat Pump & Wall Heaters)

Third Mutual is responsible for providing a heat source in the bedroom and living/dining room areas of its manors. At the time of original construction, the provided heat source was in-ceiling radiant heat systems. If an original in-ceiling radiant heat system fails or requires replacement as the result of some maintenance activity, the Mutual must provide a replacement heat source. The Mutual replaces failed heat systems with an appropriate and cost-effective type unit for the room being heated, such as placing a wall heater in the bedroom and a through-the-wall heat pump in the living room and dining room. The type of unit used is contingent on several factors, the most important being the BTU's required to heat the area being heated.

Alternate heat sources will be installed on an as-needed basis.

25) Exterior Lighting

\$12,925

Contingency funding for any needed repairs to common area lighting performed by in-house staff.

26) Fencing

\$70,757

Third has approximately 13 miles or 70,000 linear feet of decorative wooden split rail fencing throughout its property. The Mutual uses wooden split rail fencing as an inexpensive way to create decorative boundaries between buildings, as well as define sloped areas.

Staff replaces rotted split rail fencing on an as-needed basis.

27) Garden Villa Lobby

This reserve component addresses the renovation of the lobby areas of the Mutual's Garden Villa-style buildings, which is performed on a program basis. The lobby ceilings, walls, and floor coverings are inspected annually and those in the poorest condition, receive the highest priority for renovation. Member requests for lobby improvements are also considered during the evaluation process each year.

The final lobby in this program cycle was completed in 2022. The next renovations are scheduled to occur in 2026.

28) Garden Villa Mailroom

This reserve component addresses the renovation of mailrooms in the Mutual's Garden Villa style buildings. The renovation cycle was completed in 2020 and will resume in 2026. The 2025 funding is a contingency for touch-up painting of the mailroom walls.

29) Garden Villa Rec Room

(A) Water Heaters

There are 53 Garden Villa Recreation Room water heaters in the Mutual. Replacement of the water heaters is implemented proactively at the end of their 10year serviceable life.

(B) Heat Pumps

Replacement of the heat pumps is based on an annual inspection with consideration to the unit's expected lifecycle, maintenance and repair history, age and its overall condition, or upon failure. Funding increased to replace 3 heat pumps in 2025.

(C) Window Replacements

Funding is included for window replacements in 5 Garden Villa Rec Rooms.

30) Gutters

\$203,575

This reserve component is designed to address repairs and replacements of original construction building rain gutter and downspout systems on all of the Mutual's buildings that are exhibiting deterioration, as well as new installations where gutters were not originally located.

\$0

\$68,109

\$577

(A) Gutter Repairs

The gutter systems are constructed of galvanized metal pieces joined together in tenfoot-long sections or less. Typically, original gutter systems fail at the joints and corrode, which result in leaks. The funding for this program is reactive and based on resident requests.

(B) Gutter Replacement

This reserve item is designed to address the replacement of failing, original rain gutter sections, and downspout systems on all of the Mutual's buildings.

(C) New Gutter Installation

Beginning in 2020, funding was added to the annual budget for new gutter installations in order to address drainage issues and to prevent foundation erosion in conjunction with buildings on the exterior paint program.

(D) New Gutter Screen Installation

Beginning in 2025, the Board allocated funding for a multi-year phased program to install rain gutter screens on existing gutters to minimize the accumulation of debris and reduce the chances of moisture intrusion events from overflowing gutters. With a \$50k yearly allocation, approximately 2,941 linear feet of gutter screens can be installed each year on existing gutters of varying sizes throughout the Mutual.

31) Mailboxes

\$27,640

Third has approximately 6,102 individual mailboxes. The pedestal mailboxes at all the LH-21 buildings have been replaced.

Cluster mailboxes inset on the exterior walls of one- and two-story buildings are deteriorating and are no longer compliant to USPS standards. Each cluster mailbox will house 4, 8 or 12 units.

Funding is provided to replace mailbox clusters in approximately 8 buildings each year until all are compliant with USPS standards.

32) Paint Program

\$1,757,800

During the 2021 Business Planning Meeting, the Board elected to change the exterior paint program from a 10-year to a 15-year paint cycle for the 16,495,970 square feet of exterior building surfaces. All exterior components of each building are to be painted every 15 years. The building components painted include the body, (stucco and/or siding) and the trim (fascia boards, beams, overhangs, doors, closed soffits and structural and ornamental metal surfaces).

Deck top coat resurfacing, replacement of reflective address building numbers, lead testing and Lead RRP (Renovation, Repair and Painting) activities are performed in conjunction with the program. Non-wood alternatives are used where possible.

Funding also includes interior and exterior touch-up painting which was moved from Operating to Reserves in 2019.

Planned expenditures are based on the square footage of the buildings scheduled for that fiscal year. Cul-de-sacs 302, 303, 304, 406, 407, 408, 409, buildings 5318-5346 and carports 5001-5010 are planned for 2025.

33) Prior to Paint

\$1,437,585

(A) PTP

The reserve component for prior-to-paint repairs will prepare building surfaces for painting. This work is performed by outside contractors and in-house staff and includes structural and non-structural repairs; mitigation of dry rot; balcony and breezeway decking repairs which are performed every 15 years in conjunction with the exterior paint program.

(B) Top Coat Resurfacing

The elevated balcony and breezeway deck surfaces are inspected and repaired every 7.5 years, which is mid-way between the 15-year exterior paint cycle. This reserve component is designed to provide a waterproof top coat sealant to those elevated surfaces.

Funding also includes costs related to asbestos and lead testing with the abatement of dry rotted components.

Planned expenditures are based on the square footage of the buildings scheduled for that fiscal year. Proposed increase in 2025 is due to anticipated rise dry rot repair work orders.

34) Paving/Concrete

\$801,915

(A) Parkway Concrete

Each year staff inspects the Mutual sidewalks in areas scheduled to receive paving work for potential tripping hazards, and areas are identified for replacement. This helps to minimize the waiting periods for concrete repairs that are addressed by the General Services Department. Staff also identifies all damaged drainage gutters in the area and includes their replacement cost in this budget item. This program works in conjunction with the current paving program. During the 2022 Business Planning Meeting, the Third Board voted that the budget for this component be deferred in

2022. Parkway Concrete repairs resumed in 2024. 9 cul-de-sacs are planned for 2025.

(B) Asphalt Repairs

As part of the Mutual's asphalt repaving program, each year all asphalt pavement in the community is inspected and rated for wear. When the pavement rating justifies replacement, the work is budgeted for the upcoming year. For the purpose of reserve planning, an estimated life of 25 years is used. 9 cul-de-sacs are planned for 2025, which equal 105,264 square feet.

(C) Seal Coat

The application of a seal coat over asphalt is necessary to extend the useful life of pavement. Asphalt receives a seal coat 5 years after paving and also on a continuous 7-year cycle thereafter. This type of preventive maintenance is considered the most efficient and cost- effective method of extending the serviceable life of asphalt paving. 12 cul-de-sacs are planned for 2025.

(D) Golf Cart Parking & Striping

During the 2018 Business Planning meeting, staff was directed to consider additional opportunities to create golf cart parking in areas where landscaping has declined or is absent, and a pilot program was completed in Gate 14. The Board directed staff to budget \$50,000 each year to create 20 additional parking spaces with the understanding there may not be available open space to create 20 parking spaces each year. During the 2022 Business Planning Meeting, the Third Board voted that the budget for this component be cancelled until further notice.

35) Roofs

\$1,940,618

(A) Roofs Preventive Maintenance

The Built-up Roof (BUR) Maintenance Program is intended to extend the serviceable life of existing BUR roofs by three to five years, for a total serviceable life of 18-20 years. The program emphasizes aggressive repair and maintenance on BUR roofs at 5-year intervals.

The current roofing contract provides for the 5-year preventive maintenance of each roof system at no cost to the Mutual. The 10-year preventive maintenance program for 2025 includes those built-up roofs that were replaced in 2015.

(B) Roofs Built-Up – PVC Cool Roof

The Built-Up Roofing ("BUR") Replacement Program is designed to identify and replace BUR systems that have reached their serviceable life, with PVC Cool Roofs, which have a serviceable life of 25 years. All roofs 15 years of age and older are

visually inspected and a query of all reported rain leaks for the subject buildings is generated.

The roofs are ranked by condition and those with the worst overall performance are slated for replacement. Therefore, not all BURs are replaced upon expiration of their anticipated serviceable life. 17 building roofs will be replaced with a PVC Cool Roof system in 2025.

(C) Roofs Lightweight Tile (LWT) to Comp Shingle

In 1990, buildings with wood shake roof systems were re-roofed with Lightweight Tile (LWT) to eliminate the potential fire hazard of the wood shake roof. (377 buildings, totaling 1,438,052 square feet).

LWT roofs have required significant maintenance since 2010 and are considered to be failing.

In 2020, the LWT roofs began to be re-roofed with Composition Shingles. Staff recommended a 15-year phased plan starting in 2020 to replace the LWT with Comp Shingles. 5 building roofs will be replaced with Composition Shingles in 2025.

36) Exterior Walls

Barbed wire is no longer a city-approved material for wall security. In 2017, the City of Laguna Woods passed a resolution to include Shepherd's Crook as an acceptable replacement to the existing barbed wire. Beginning in 2020, expenditures included the cost of clearing and grubbing.

The Village is required by the Condition Use Permit (CUP) to replace at least 900 lineal feet per year of barbed wire.

At the Board's request, funding for this work has been removed until further notice.

37) Waste Line Remediation

\$1,500,000

\$0

In 2006, the Board established a reserve line item for waste lines. The program provides for the evaluation of waste lines and the establishment and implementation of a strategy for replacement. Lining the underground and under slab pipe is possible with a liner and epoxy resin product. The program was expanded to include interior pipes in 2017.

7 Garden Villa buildings will receive waste line remediation in 2025.

38) Water Lines – Copper Pipe Remediation

In 2006, the Board established a reserve line item for copper water lines. This budget item funds the epoxy lining of copper water supply lines in the Mutual.

8 buildings will receive copper pipe epoxy lining in 2025.

Pressure Regulators: The Board voted to allocate \$200,000 per year for pressure regulator installation/replacements for the (General) Plumbing Replacement Reserve Funds (RPF) beginning in 2023. Pressure regulators will be installed to reduce the high pressure found at manors measuring over 80psi at Third Mutual buildings. The cost of the pressure regulator depends on size, ranging from 3/4" to 2", and will be installed/replaced on an as-needed basis.

Installation of 100 pressure regulator valves are planned for in 2025.

40) Eleva	ators
-----------	-------

The Elevator Replacement Fund provides funding for component replacement and interior cab upgrades to the 82 passenger elevators in the Mutual. Elevator flooring replacement expenditures are a contingency and will only be replaced as needed.

In 2025, 3 elevators will be scheduled for maintenance and interior cab upgrades.

41)	Laundry Countertop/Floor	Replacement	\$42,414
-----	--------------------------	-------------	----------

(A) Countertops

The laundry facilities in Third are comprised of 81 three-story buildings with three laundry rooms each and 44 freestanding laundry rooms. The three-story building laundry rooms have one folding table that will be replaced with a wall mounted countertop. The free-standing laundry rooms have four wall mounted countertops and are treated as one component for reserve purposes. The current replacement policy is reactive and countertops are replaced upon failure or non-reparability.

Estimated Life = 20 Years. Planned expenditures are based on the historical replacement quantities, anticipated useful life, and current estimated cost, plus inflation.

(B) Flooring

There are three laundry facilities, one on each floor, of Third's 81 three-story buildings

\$205,800

\$200,000

for a total of 243. Each of these laundry facilities has sheet vinyl floor covering. The Laundry Room Flooring Program allows the existing vinyl flooring to be professionally removed by an abatement contractor, staff then applies an epoxy floor coating over the entire surface.

Estimated Life = 25 years. Planned expenditures are based on the historical replacement quantities, anticipated life, and current estimated costs, plus inflation.

42) Laundry Appliances

\$164,499

(A) Water Heaters

There are 125 laundry room water heaters in the Mutual. The Mutual's policy is to replace all water heaters in their 10th year of life. Planned expenditures are based on the anticipated useful life and current estimated cost of materials and labor plus inflation.

(B) Dryers

There are 373 commercial, coin operated dryers in stand-alone laundry facilities and 3-story buildings. The dryers have been placed on pedestals for easier use.

(C) Washers

There are 455 washers in the Mutual's stand-alone and 3-story building laundry facilities. The washing machines in 3-story buildings have been placed on pedestals for easier use. The current replacement policy is reactive and washers are replaced upon failure or non-reparability.

In 2024, the Board approved changing the washing machine brand from Maytag to Speed Queen for better durability and efficiency. Existing Maytag washing machines are replaced with Speed Queen upon failure. The 2025 budget reflects the increased material cost for Speed Queen washing machines and laundry pedestals.

\$15,263

\$86,279

\$24,150

THIRD LAGUNA HILLS MUTUAL 2025 RESERVE EXPENDITURES GENERAL SERVICES

This section covers the inspection, maintenance and repair of metal work (prior to paint), paving and concrete, and repair to common area and perimeter walls. Primarily these maintenance items are in response to resident service requests, although many items are planned program work.

43) Prior to Paint

Third Mutual has a 15-year full exterior paint program. This budget item includes a contingency for metal work performed by General Services Welders, including railing, stairway, and balcony railing metal work, and other welding repairs on the buildings scheduled for the 2025 exterior paint program.

 WC 936 Street and Sidewalks will need to address metal issues in about 15% of the buildings

44) Paving/Concrete

Funding provided in this section is used to fund general asphalt repair work, excavation related to mainline repair, and crack filling work that is completed in conjunction with Maintenance and Construction's planned slurry seal program.

45) Exterior Walls

This is a contingency for both perimeter and common wall replacements.

Funding is provided in this item to address common area walls, as well as Third's perimeter walls that are damaged by tree roots, deterioration, and other causes.

(A) Common Area

This budget line item provides contingency funding for repairs to the common interior walls in the Mutual. This program addresses the need to provide common wall repair or replacement throughout the community.

(B) Perimeter

Third Laguna Hills Mutual utilizes perimeter walls to provide physical security. The majorities of the walls were built over 35 years ago, and is typically made of concrete block. In addition to providing security to the community, this program replaces walls due to damage or deterioration.

46-48) Landscape Services

These items will be reviewed at the Landscape budget meeting.

THIRD LAGUNA HILLS MUTUAL 2025 PLAN PROGRAMS REPORT

	DESCRIPTION	2021 ACTUALS	2022 ACTUALS	2023 ACTUALS	2024 BUDGET	2025 BUDGET	LABOR	MATERIALS	OUTSIDE SERVICES	HOURS	Assessm Increase/(Dec \$	
			DI	SASTER FUND	- MAINTENANC	E & CONSTRU	CTION					-
49	MOISTURE INTRUSION - RAIN LEAKS	\$253,951	\$242,184	\$545,258	\$220,000	\$220,000	\$0	\$0	\$220,000	0	\$0	0%
909	A991000000 - OS	253,951	242,184	545,258	220,000	220,000	0	0	220,000	0	0	0%
50	MOISTURE INTRUSION - PLUMBING LEAKS	\$614,090	\$183,156	\$844,881	\$650,000	\$800,000	\$0	\$0	\$800,000	0	\$150,000	23%
909	A992000000 - OS	1,237,850	180,544	844,881	650,000	800,000	0	0	800,000	0	150,000	23%
909	Miscellaneous	(623,760)	2,612	0	0	0	0	0	0	0		
51	MOISTURE INTRUSION - PLUMBING STOPPAGES	\$118,104	\$141,150	\$197,739	\$80,000	\$152,000	\$0	\$0	\$152,000	0	\$72,000	90%
909	A993000000 - OS	118,104	141,150	197,739	80,000	152,000	0	0	152,000	0	72,000	90%
52	MOISTURE INTRUSION - MISCELLANEOUS	\$14,507	\$49,599	\$62,836	\$50,000	\$42,000	\$0	\$0	\$42,000	0	(\$8,000)	(16%)
909	A994000000 - OS	14,507	49,599	62,836	50,000	42,000	0	0	42,000	0	(8,000)	(16%)
53	DAMAGE RESTORATION SERVICES	\$162,802	\$165,336	\$41,956	\$50,280	\$29,384	\$24,384	\$5,000	\$0	300	(\$20,896)	(42%)
912	A380080000	43,514	36,043	41,956	50,280	29,384	24,384	5,000	0	300	(20,896)	(42%)
925	A31006OS61	(21,185)	0	0	0	0	0	0	0	0	0	
925	Various Historical Jobs	140,642	126,759	0	0	0	0	0	0	0	0	0%
909	Miscellaneous	54,858	0	0	0	0	0	0	0	0		
	TOTAL	#4 400 454										
	TOTAL	\$1,163,454	\$781,424	\$1,692,671	\$1,050,280	\$1,243,384	\$24,384	\$5,000	\$1,214,000	300	\$193,104	18%
56			GARDEN V	ILLA REC ROO	M FUND - MAIN	TENANCE & CO	DNSTRUCTION					
56	GARDEN VILLA RECREATION ROOMS	\$70,118	GARDEN V \$82,796	/ILLA REC ROO \$94,246	M FUND - MAIN \$97,502	TENANCE & CO \$128,605	DNSTRUCTION \$29,327	\$29,278	\$70,000	0	\$31,103	32%
910	GARDEN VILLA RECREATION ROOMS A310050000 - GV Rec Room Misc. Services	\$70,118 38,852	GARDEN V	/ILLA REC ROO \$94,246 51,434	M FUND - MAIN \$97,502 57,750	TENANCE & CO \$128,605 70,000	ONSTRUCTION \$29,327 0	\$29,278 0		0 0	\$31,103 12,250	32% 21%
910 912	GARDEN VILLA RECREATION ROOMS A310050000 - GV Rec Room Misc. Services A320090000 Carpentry Service Garden Villa Interior	\$70,118 38,852 965	GARDEN V \$82,796	/ILLA REC ROO \$94,246 51,434 3,721	M FUND - MAIN \$97,502 57,750 5,498	TENANCE & CO \$128,605 70,000 5,640	DNSTRUCTION \$29,327 0 3,990	\$29,278 0 1,650	\$70,000	0	\$31,103 12,250 142	32% 21% 3%
910 912 911	GARDEN VILLA RECREATION ROOMS A310050000 - GV Rec Room Misc. Services A320090000 Carpentry Service Garden Villa Interior A350110000 Appliance PM Garden Villa Rec Rooms	\$70,118 38,852 965 81	GARDEN V \$82,796	/ILLA REC ROO \$94,246 51,434 3,721 301	M FUND - MAIN \$97,502 57,750 5,498 566	TENANCE & CO \$128,605 70,000 5,640	ONSTRUCTION \$29,327 0 3,990 360	\$29,278 0 1,650 223	\$70,000	0 0	\$31,103 12,250 142 16	32% 21% 3% 3%
910 912 911 911	GARDEN VILLA RECREATION ROOMS A310050000 - GV Rec Room Misc. Services A320090000 Carpentry Service Garden Villa Interior A350110000 Appliance PM Garden Villa Rec Rooms A350120000 Appliance Replc. Garden Villa Rec Rooms	\$70,118 38,852 965 81 0	GARDEN V \$82,796	VILLA REC ROO \$94,246 51,434 3,721 301 301	M FUND - MAIN \$97,502 57,750 5,498 566 343	TENANCE & CO \$128,605 70,000 5,640 583 360	DNSTRUCTION \$29,327 0 3,990 360 360 360	\$29,278 0 1,650 223 0	\$70,000	0 0	\$31,103 12,250 142 16 16	32% 21% 3% 3% 5%
910 912 911 911 913	GARDEN VILLA RECREATION ROOMS A310050000 - GV Rec Room Misc. Services A320090000 Carpentry Service Garden Villa Interior A350110000 Appliance PM Garden Villa Rec Rooms A350120000 Appliance Replc. Garden Villa Interior	\$70,118 38,852 965 81 0 726	GARDEN V \$82,796	VILLA REC ROO \$94,246 51,434 3,721 301 301 584	M FUND - MAIN \$97,502 57,750 5,498 566 343 734	TENANCE & CO \$128,605 70,000 5,640 583 360 754	DNSTRUCTION \$29,327 0 3,990 360 360 360 599	\$29,278 0 1,650 223 0 155	\$70,000	0 0	\$31,103 12,250 142 16 16 21	32% 21% 3% 3% 5% 3%
910 912 911 911 913 914	GARDEN VILLA RECREATION ROOMS A310050000 - GV Rec Room Misc. Services A320090000 Carpentry Service Garden Villa Interior A350110000 Appliance PM Garden Villa Rec Rooms A350120000 Appliance Replc. Garden Villa Rec Rooms A340090000 Electrical Service Garden Villa Interior A370090000 Repair/Replace Garden Villa Rec Rooms	\$70,118 38,852 965 81 0 726 0	GARDEN V \$82,796	VILLA REC ROO \$94,246 51,434 3,721 301 301 301 304 584 466	M FUND - MAIN \$97,502 57,750 5,498 566 343 734 837	TENANCE & CO \$128,605 70,000 5,640 583 360 754 904	DNSTRUCTION \$29,327 0 3,990 360 360 599 554	\$29,278 0 1,650 223 0 155 350	\$70,000	0 0	\$31,103 12,250 142 16 16 21 67	32% 21% 3% 3% 5% 3% 8%
910 912 911 911 913 914 914	GARDEN VILLA RECREATION ROOMS A310050000 - GV Rec Room Misc. Services A320090000 Carpentry Service Garden Villa Interior A350110000 Appliance PM Garden Villa Rec Rooms A350120000 Appliance Replc. Garden Villa Rec Rooms A340090000 Electrical Service Garden Villa Interior A370090000 Repair/Replace Garden Villa Interior	\$70,118 38,852 965 81 0 726 0 1,378	GARDEN V \$82,796 55,386 8 0 0 0 0 0 0 0 0	/ILLA REC ROO \$94,246 51,434 3,721 301 301 584 466 2,798	M FUND - MAIN \$97,502 57,750 5,498 566 343 734 837 3,828	TENANCE & CO \$128,605 70,000 5,640 583 360 754	DNSTRUCTION \$29,327 0 3,990 360 360 599 554 3,049	\$29,278 0 1,650 223 0 155 350 800	\$70,000	0 0	\$31,103 12,250 142 16 16 21 67 21	32% 21% 3% 5% 3% 8% 1%
910 912 911 911 913 914 914 914	GARDEN VILLA RECREATION ROOMS A310050000 - GV Rec Room Misc. Services A320090000 Carpentry Service Garden Villa Interior A350110000 Appliance PM Garden Villa Rec Rooms A350120000 Electrical Service Garden Villa Interior A370090000 Electrical Service Garden Villa Interior A370090000 Plumbing Service Garden Villa Interior A97225925 Replace Vinyl Floors in GV Rec Rooms	\$70,118 38,852 965 81 0 726 0 1,378 0	GARDEN V \$82,796 55,386 0 0 0 0 0 0 0 0 0 0 0 0 0	/ILLA REC ROO \$94,246 51,434 3,721 301 584 466 2,798 1,887	M FUND - MAIN \$97,502 57,750 5,498 566 343 734 837 3,828 0	TENANCE & CC \$128,605 70,000 5,640 583 360 754 904 3,849 0	DNSTRUCTION \$29,327 0 3,990 360 360 360 599 554 3,049 0	\$29,278 0 1,650 223 0 155 350 800 0	\$70,000	0 0	\$31,103 12,250 142 16 16 21 67 21 0	32% 21% 3% 5% 3% 8% 1% 0%
910 912 911 913 913 914 914 917 917	GARDEN VILLA RECREATION ROOMS A31005000 - GV Rec Room Misc. Services A320090000 Carpentry Service Garden Villa Interior A350110000 Appliance PM Garden Villa Rec Rooms A350120000 Appliance Replc. Garden Villa Rec Rooms A340090000 Electrical Service Garden Villa Interior A370090000 Repair/Replace Garden Villa Interior A917259925 Replace Vinyl Floors in GV Rec Rooms A917270000 Receation Room Refurbishment	\$70,118 38,852 965 81 0 726 0 1,378 0 4,128	GARDEN V \$82,796 55,386 8 0 0 0 0 0 4,157	VILLA REC ROO \$94,246 51,434 3,721 301 301 584 466 2,798 1,687 10,463	M FUND - MAIN \$97,502 57,750 5,498 566 343 734 837 3,828 0 11,131	TENANCE & CC \$128,605 70,000 5,640 583 360 754 904 3,849 0 11,468	DNSTRUCTION \$29,327 0 3,990 360 360 599 554 3,049 0 6,468	\$29,278 0 1,650 223 0 155 350 800 0 0 5,000	\$70,000	0 0	\$31,103 12,250 142 16 21 67 21 0 338	32% 21% 3% 5% 3% 8% 1% 0% 3%
910 912 911 913 913 914 914 917 917 917	GARDEN VILLA RECREATION ROOMS A310050000 - GV Rec Room Misc. Services A320090000 Carpentry Service Garden Villa Interior A350110000 Appliance PM Garden Villa Rec Rooms A340090000 Electrical Service Garden Villa Interior A370090000 Repair/Replace Garden Villa Interior A370090000 Plumbing Service Garden Villa Interior A917259925 Replace Vinyl Floors in GV Rec Rooms A917270000 Recreation Room Refurbishment A917290000 Garden Villa Replacements	\$70,118 38,852 965 81 0 726 0 1,378 0 4,128 1,102	GARDEN V \$82,796 55,386 8 0 0 0 0 0 4,157 0	/ILLA REC ROO \$94,246 51,434 3,721 301 301 584 466 2,798 1,687 10,463 1,646	M FUND - MAIN \$97,502 57,750 5,498 566 343 734 837 3,828 0 11,131 987	TENANCE & CC \$128,605 70,000 5,640 583 360 754 904 3,849 0 11,468 1,892	DNSTRUCTION \$29,327 0 3,990 360 360 360 599 554 3,049 0 6,468 892	\$29,278 0 1,650 223 0 155 350 800 0 5,000 1,000	\$70,000	0 0	\$31,103 12,250 142 16 16 21 67 21 0 338 906	32% 21% 3% 3% 5% 3% 8% 1% 0% 3% 92%
910 912 911 913 913 914 914 917 917 917 917	GARDEN VILLA RECREATION ROOMS A31005000 - GV Rec Room Misc. Services A32009000 Carpentry Service Garden Villa Interior A350110000 Appliance PM Garden Villa Rec Rooms A340090000 Electrical Service Garden Villa Interior A370090000 Electrical Service Garden Villa Interior A370090000 Repair/Replace Garden Villa Interior A370200000 Plumbing Service Garden Villa Interior A91725925 Replace Vinyl Floors in GV Rec Rooms A917270000 Recreation Room Refurbishment A917290000 Garden Villa Replacements A917510000 Refrigerator Install/Replacement	\$70,118 38,852 965 81 0 726 0 1,378 0 4,128 1,102 1,693	GARDEN V \$82,796 55,386 8 0 0 0 0 0 0 0 0 0 0 4,157 0 0	/ILLA REC ROO \$94,246 51,434 3,721 301 301 584 466 2,798 1,687 10,463 1,646 0	M FUND - MAIN \$97,502 57,750 5,498 566 343 734 837 3,828 0 11,131 987 800	TENANCE & CC \$128,605 70,000 5,640 583 360 754 904 3,849 0 11,468 1,892 800	DNSTRUCTION \$29,327 0 3,990 360 360 599 554 3,049 0 6,468	\$29,278 0 1,650 223 0 155 350 800 0 5,000 1,000 800	\$70,000	0 0	\$31,103 12,250 142 16 16 21 67 21 0 338 906 0	32% 21% 3% 3% 5% 3% 8% 1% 0% 3% 9% 9% 0%
910 912 911 913 914 914 917 917 917 917 917	GARDEN VILLA RECREATION ROOMS A31005000 - GV Rec Room Misc. Services A320090000 Carpentry Service Garden Villa Interior A350110000 Appliance PM Garden Villa Rec Rooms A350120000 Electrical Service Garden Villa Rec Rooms A370090000 Repair/Replace Garden Villa Interior A370090000 Repair/Replace Garden Villa Interior A917259925 Replace Vinyl Floors in GV Rec Rooms A917270000 Receation Room Refurbishment A917290000 Garden Villa Replacements A917520000 Rarigerator Install/Replacement A917520000 Range Install/Replacement	\$70,118 38,852 965 81 0 726 0 1,378 0 4,128 1,102 1,693 2,030	GARDEN V \$82,796 55,386 8 0 0 0 0 0 0 4,157 0 2,759	VILLA REC ROO \$94,246 51,434 3,721 301 584 466 2,798 1,687 10,463 1,646 0 6,487	M FUND - MAIN \$97,502 57,750 5,498 566 343 734 837 3,828 0 11,131 987 800 1,788	TENANCE & CC \$128,605 70,000 5,640 583 360 754 904 3,849 0 11,468 1,892 800 7,000	DNSTRUCTION \$29,327 0 3,990 360 360 360 599 554 3,049 0 6,468 892	\$29,278 0 1,650 223 0 155 350 800 0 5,000 1,000 800 7,000	\$70,000	0 0	\$31,103 12,250 142 16 16 21 67 21 0 338 906 0 5,202	32% 21% 3% 3% 5% 8% 1% 0% 3% 92% 0% 289%
910 912 911 913 914 914 917 917 917 917 917 917 917	GARDEN VILLA RECREATION ROOMS A310050000 - GV Rec Room Misc. Services A320090000 Carpentry Service Garden Villa Interior A350110000 Appliance PM Garden Villa Rec Rooms A340090000 Repair/Replace Garden Villa Interior A370090000 Repair/Replace Garden Villa Interior A370090000 Repair/Replace Garden Villa Interior A917259925 Replace Vinyl Floors in GV Rec Rooms A917250000 Recreation Room Refurbishment A917250000 Recreation Room Refurbishment A917510000 Refrigerator Install/Replacement A917520000 Range Install/Replacement A917520000 Range Install/Replacement	\$70,118 38,852 965 81 0 726 0 1,378 0 4,128 1,102 1,693 2,030 2,248	GARDEN V \$82,796 55,386 8 0 0 0 0 0 0 0 0 0 0 0 0 0	/ILLA REC ROO \$94,246 51,434 3,721 301 301 584 466 2,798 1,687 10,463 1,646 0 6,487 2,326	M FUND - MAIN \$97,502 57,750 5,498 566 343 734 837 3,828 0 11,131 987 800 1,798 1,023	TENANCE & CC \$128,605 70,000 5,640 583 360 754 904 3,849 0 0 11,468 1,892 800 7,000 2,500	DNSTRUCTION \$29,327 0 3,990 360 360 360 599 554 3,049 0 6,468 892 0 0 0 0 0 0 0 0 0 0 0 0 0	\$29,278 0 1,650 223 0 155 350 800 0 5,000 1,000 800 7,000 2,500	\$70,000	0 0	\$31,103 12,250 142 16 16 21 67 21 0 338 906 0 5,202 1,477	32% 21% 3% 3% 5% 8% 1% 0% 9% 0% 289% 144%
910 912 911 913 914 914 917 917 917 917 917 917 917 917	GARDEN VILLA RECREATION ROOMS A31005000 - GV Rec Room Misc. Services A32009000 Carpentry Service Garden Villa Interior A350110000 Appliance PM Garden Villa Rec Rooms A350120000 Electrical Service Garden Villa Interior A370090000 Electrical Service Garden Villa Interior A370090000 Pleumbing Service Garden Villa Interior A370290000 Pleumbing Service Garden Villa Interior A91725925 Replace Vinyl Floors in GV Rec Rooms A917270000 Recreation Room Refurbishment A917510000 Rarden Villa Replacements A917520000 Range Install/Replacement A917550000 Sink Install/Replacement A917550000 Sink Install/Replacement	\$70,118 38,852 965 81 0 726 0 1,378 0 4,128 1,102 1,693 2,030 2,248 3,404	GARDEN V \$82,796 55,386 8 0 0 0 0 0 0 4,157 0 2,759	VILLA REC ROO \$94,246 51,434 3,721 301 584 466 2,798 1,687 10,463 1,646 0 6,487	M FUND - MAIN \$97,502 57,750 5,498 566 343 734 837 3,828 0 11,131 987 800 1,798 1,023 964	TENANCE & CC \$128,605 70,000 5,640 583 360 754 904 3,849 0 11,468 1,892 800 7,000 2,500 7,102	DNSTRUCTION \$29,327 0 3,990 360 360 360 599 554 3,049 0 6,468 892 0 0 0	\$29,278 0 1,650 223 0 155 350 800 0 5,000 1,000 800 7,000 2,500 4,500	\$70,000	0 0	\$31,103 12,250 142 16 16 21 67 21 0 338 906 0 5,202	32% 21% 3% 3% 5% 3% 8% 0% 9% 0% 289% 0% 289% 0% 289% 637%
910 912 911 913 914 914 917 917 917 917 917 917 917	GARDEN VILLA RECREATION ROOMS A310050000 - GV Rec Room Misc. Services A320090000 Carpentry Service Garden Villa Interior A350110000 Appliance PM Garden Villa Rec Rooms A340090000 Repair/Replace Garden Villa Interior A370090000 Repair/Replace Garden Villa Interior A370090000 Repair/Replace Garden Villa Interior A917259925 Replace Vinyl Floors in GV Rec Rooms A917250000 Recreation Room Refurbishment A917250000 Recreation Room Refurbishment A917510000 Refrigerator Install/Replacement A917520000 Range Install/Replacement A917520000 Range Install/Replacement	\$70,118 38,852 965 81 0 726 0 1,378 0 4,128 1,102 1,693 2,030 2,248	GARDEN V \$82,796 55,386 8 0 0 0 0 0 0 0 0 0 0 0 0 0	/ILLA REC ROO \$94,246 51,434 3,721 301 584 466 2,798 1,687 10,463 1,646 0 6,487 2,326 3,905	M FUND - MAIN \$97,502 57,750 5,498 566 343 734 837 3,828 0 11,131 987 800 1,798 1,023	TENANCE & CC \$128,605 70,000 5,640 583 360 754 904 3,849 0 0 11,468 1,892 800 7,000 2,500	DNSTRUCTION \$29,327 0 3,990 360 360 599 554 3,049 0 6,468 892 0 0 0 2,602	\$29,278 0 1,650 223 0 155 350 800 0 5,000 1,000 800 7,000 2,500	\$70,000	0 0	\$31,103 12,250 142 16 16 21 67 21 0 338 906 0 5,202 1,477 6,138	32% 21% 3% 5% 3% 8% 1% 0% 3% 92% 0% 289% 144%

THIRD LAGUNA HILLS MUTUAL 2025 DISASTER EXPENDITURES MAINTENANCE AND CONSTRUCTION

This was one of the first funds established for the Mutual to reserve for contingencies and uninsured damages. The purpose of this fund is to provide for emergency expenditures or catastrophic damages not covered by insurance, including insurance policy deductible amounts. Also, possibly for write-offs of uncollectible accounts according to original definition of the General Operating Fund. In the 2009 Business Plan, this fund was renamed from the General Operating Fund to the Disaster Fund to better convey its purpose. This fund is not required by Civil Code and is therefore excluded from reserve plan calculations.

49) Moisture Intrusion – Rain Leaks

This line item funds remediation (dry down, environmental testing, abatement & misc. repairs) of manors due to roof leaks, deteriorated roof membranes, roof flashing/connections, windows, stucco walls, atrium back-ups, gutter systems, rain flooding, skylights (non-alteration), and vents, that may cause damage to the Mutual's asset and require repairs. If replacements are needed, those items will be funded from the Replacement/Reserve fund.

50) Moisture Intrusion – Plumbing Leaks

This line item funds remediation (dry down, environmental testing, abatement & misc. repairs) of manors due to plumbing leaks from the under-slab, in-wall, supply line, and drain line, that may cause damage to the Mutual's asset and require repairs. If replacements are needed, those items will be funded from the Replacement/Reserve fund.

51) Moisture Intrusion – Plumbing Stoppages

This line item funds remediation (dry down, environmental testing, abatement & misc. repairs) of manors due to plumbing stoppages from main lines, internal lines, toilets, sink and basins that may cause damage to the Mutual's asset and require repairs. If replacements are needed, those items will be funded from the Replacement/Reserve fund.

Moisture Intrusion – Miscellaneous 52)

This line item funds remediation (dry down, environmental testing, abatement & misc. repairs) of units with miscellaneous moisture intrusion from tub/shower enclosures, cracked tile, missing grout, humidity, irrigation, loose sink/countertop connections, common area washing machines, foundations, window condensation, and mold, that may cause damage to the Mutual's asset and require repairs. If replacements are needed, those items will be funded from the Reserve Fund.

\$800,000

\$152,000

\$220,000

\$42,000

53) Damage Restoration Services

This line item funds the emergency repairs due to damage from structure fires and vehicle accidents.

If replacements are needed, those items will be funded from the Replacement/Reserve fund. Funding levels for this category are based on historic averages.

Part of this expenditure is reimbursed to the Mutual through hearings that review the circumstances of the moisture intrusion event in order to determine if the member should be held responsible for costs associated with the restoration.

54-55) Landscape and Financial Services

Line 54 will be reviewed at the Landscape budget meeting. Line 55 is unfunded in 2025.

THIRD LAGUNA HILLS MUTUAL 2025 GARDEN VILLA REC ROOM EXPENDITURES MAINTENANCE AND CONSTRUCTION

56) Garden Villa Recreation Rooms

\$128,605

The Replacement Reserve-Villa Furnishings Fund was established in 1975 for the replacement of furnishings in the Villa buildings. Several policy changes were made through the years regarding the fund name and usage. On September 19, 1995, the Board of Directors adopted Resolution M3-95-82 approving a fund name of Garden Villa Recreation Room Fund.

The purpose of this fund is to provide for all expenditures in the recreation rooms of Garden Villa buildings (repairs, replacements and preventive maintenance), other than janitorial services.

On June 16, 2009 the Board directed that water heater and heat pump components previously paid from this fund will be paid from the Replacement Fund.



Laguna Woods Village®

Budget Calendar for Development of the 2025 Business Plan

DESCRIPTION	GRF Board	United Board	Third Board
Review	of Existing (2024)	Service Levels	
Department Workshops	Wed Mar 13 9:30 A.M.		
Landscape, Maintenance, and General Services Review		Mon Apr 8 9:30 A.M.	Wed Mar 27 1:30 P.M.
	Internal Revi	ew	
Reserves / Capital		April / May	
	Version 1		
Capital Review	Wed May 15 1:30 P.M.		
Operating Department Review	Wed May 29 1:30 P.M.		
Maintenance & General Services Review		Thu May 23 1:30 P.M.	Thu May 23 9:30 A.M.
Landscape Review		Mon Jun 3 9:30 A.M.	Mon Jun 3 1:30 P.M.
Capital Or Operating Review (if necessary)	Mon Jun 17 1:30 P.M.		
	Version 2		
Business Plan		for Changes June	*
Preparation		das Wednesday J	
Business Plan Review	Wed Jul 10	Wed Jul 17	Mon Jul 15
	1:30 P.M. Version 3	1:30 P.M.	9:30 am
Business Plan		for Changes July	24. 2024
Preparation		das Thursday Aug	ţ.
Business Plan Review	Mon Aug 5	Mon Aug 12	Mon Aug 19
(Televised)	9:30 A.M.	1:30 P.M.	1:30 P.M.
	Proposed Fin	al	
Business Plan Adoption	Tue Sept 3 9:30 A.M.	Tue Sept 10 9:30 A.M.	Tue Sept 17 9:30 A.M.



		-	-				
	2021	2022	2023	2024	2025		
FUND	Actual	Actual	Actual	Budget	Budget	\$ Change	% Chang
Operating	\$ 1,861,209	\$ 1,689,487	\$ 1,998,581	\$ 2,203,975	\$ 2,551,990	\$ 348,015	16%
Reserve	\$ 8,053,489	\$ 7,247,341	\$ 8,508,089	\$10,620,819	\$11,982,357	\$ 1,361,539	13%
Disaster	\$ 1,163,454	\$ 781,424	\$ 1,692,671	\$ 1,050,280	\$ 1,243,384	\$ 193,104	18%
Subtotal	\$11,078,152	\$ 9,718,343	\$12,199,341	\$13,875,074	\$15,777,731	\$ 1,902,658	14%
GV Rec Room	\$ 70,118	\$ 82,796	\$ 94,246	\$ 97,502	\$ 128,605	\$ 31,103	32%
TOTAL	\$11,148,270	\$9,801,139	\$12,293,587	\$13,972,576	\$15,906,336	\$1,933,761	14%



2025 Operating: Plumbing Services					
2023 Actual \$782,052 2024 Adopted \$786,186 • Leak investigations • In-wall leak repairs • Under-slab leaks					
 2025 (Prelim) \$844,762 Stoppages Valve/fitting repair/replacement 					
Increase/(Decrease) \$58,576 % Change 7%					
Proposed increase based on need for outside contract services and anticipated rise in labor and material costs. Plumbing Services work center completed 16,793 work order tickets in 2023; 4,600 in Third.					


2025 Operati	ng: Car	pentry Services			
2023 Actual	\$625,276	 Carport structure and garage door repair Common area window & door repair 			
2024 Adopted	\$586,661	 Common area acoustic ceiling repair Stucco, drywall/texture repair 			
2025 (Prelim)	\$592,461	Insect screen installation and repair			
Increase/(Decrease)	\$5,800				
% Change	1%				
Proposed increase based on an anticipated rise in material costs. Carpentry Services work center completed 9,108 work order tickets in 2023; 3,260 in Third.					


2025 Operating: Pest (Control
2023 Actual \$335,580	 3-year termite inspection program Resale & miscellaneous termite inspections
2024 Adopted \$377,116	 Local termite treatments & bee removal Whole-structure fumigation program
2025 (Prelim) \$655,000	 Lodging for fumigation program Plant removal for fumigation program
Increase/(Decrease) \$277,884	 53 structure fumigations in 2024 107 structure fumigations in 2025
% Change 74%	107 structure furnigations in 2025
Proposed increase based on number of b increased number of hotel stays.	uildings requiring tenting in 2025 and corresponding


2025 Operatii	ng: Fire	Protection THIRD LAGUNA HILLS
2023 Actual	\$78,254	 Fire alarm system inspections
2024 Adopted	\$151,185	Fire extinguisher serviceSprinkler system service
2025 (Prelim)	\$154,868	Standpipe testingChimney cleaning
Increase/(Decrease)	\$3,683	 Dryer Vent cleaning
% Change	2%	
Proposed increase based o	on anticipated	rise in labor and material cost. 7

2025 Operating: Electr	ical Service
2023 Actual \$31,511	Common area lighting repairs
2024 Adopted \$104,443	 Common area electrical outlet repairs Main breaker, circuit breaker repairs
2025 (Prelim) \$99,030	 Doorbell light repairs
Increase/(Decrease) (\$5,414)	
% Change (5%)	
	on of staff hours based on work order history. 576 work order tickets in 2023; 1,842 in Third. 8

2025 Operating: Appliance Repairs
2023 Actual \$73,374 • Laundry room washer repairs
• Laundry room dryer repairs
2025 (Prelim) \$118,869
Increase/(Decrease) \$3,486
% Change 3%
Proposed increase based on anticipated rise in materials costs. Appliance services work center completed 5,198 work order tickets in 2023; 1,506 in Third. 9









Description	2023 Actual	2024 Budget	2025 Prelim Budget	Increase / (Decrease)	% Change
Plumbing Service	\$782,057	\$786,186	\$844,762	\$58,576	7%
Carpentry Service	\$625,276	\$586,661	\$592,461	\$5 <i>,</i> 800	1%
Pest Control	\$335,580	\$377,116	\$655,000	\$277,884	74%
Fire Protection	\$78,254	\$151,185	\$154,868	\$3,683	2%
Electrical Service	\$31,511	\$104,443	\$99,030	(\$5,414)	(5%)
Appliance Repairs	\$73,374	\$115,384	\$118,869	\$3,486	3%
Misc. Outside Services	\$9,067	\$30,000	\$30,000	\$0	0%
Solar Maintenance	\$50,516	\$36,000	\$37,000	\$1,000	3%
Street Light Maintenance	\$12,946	\$17,000	\$20,000	\$3,000	18%
Total	\$1,998,581	\$2,203,975	\$2,551,990	\$348,015	16%




2025 Reserve	s: Buildi	ng Structures
2023 Actual	\$2,403,923	 Dry rot remediation Foundation and building settlement
2024 Adopted	\$2,300,426	 Balcony, ramp, walkway replacement
2025 (Prelim)	\$2,486,143	 Trellis, beam structure replacement Garage door, carport panel replacement CV represent kitchen, bethroom flooring
Increase/(Decrease)	\$185,717	 GV rec room kitchen, bathroom flooring Asbestos/lead abatement and testing
% Change	8%	
Proposed increase prima	rily due to \$185,	000 increase for dry rot contract services.




2025 Reserve	s: Exte	rior Lighting
2023 Actual	\$12,062	 Common area light repairs, upgrades
2024 Adopted	\$12 <i>,</i> 500	
2025 (Prelim)	\$12,925	
Increase/(Decrease)	\$425	
% Change	3%	
Contingency funding for re	pairs and upg	grades. 17




2025 Reserves:	Garder	n Villa Mailroom
2023 Actual	\$293	 53 Garden Villa buildings
2024 Adopted	\$562	 Mailroom renovations completed in 2020
2025 (Prelim)	\$577	 Mailroom renovations scheduled to resume in 2026
Increase/(Decrease)	\$15	
% Change	3%	
Contingency for touch-up pair	nt, if needed.	19




2025 Reserves	s: Gutte	THIRD LAGUNA HILLS
2023 Actual 2024 Adopted	\$67,264 \$126,486	 Repair existing rain gutters, downspouts New gutter installations for drainage issues
2025 (Prelim)	\$203,575	 Implementation of new gutter screen program 202 convice orders completed in 2022
Increase/(Decrease) % Change	\$77,089 61%	 203 service orders completed in 2023
Funding increase due to new gutter screen instal		rise in labor and material costs, as well as \$50,000 for




2025 Reserves: Paint Progra	am THIRD LAGUNA HILLS		
2023 Actual \$1,445,812 •	16.5 million s.f. of exterior surfaces		
• 2024 Adopted \$1,613,075	Paint stucco, siding, fascia boards, beams, overhangs, doors, closed soffits, and ornamental metal surfaces		
2025 (Prelim) \$1,757,800	Address signs replaced with large		
Increase/(Decrease) \$144,725	reflective building signs Touch-up painting as-needed		
% Change 9%			
Proposed increase due to anticipated rise in labor and material costs. Cul-de-sacs 302, 303, 304, 406, 407, 408, 409, buildings 5318-5346 and carports 5001-5010 are planned for 2025.			




2025 Reserve	es: Pavi	ng/Concrete
2023 Actual 2024 Adopted	\$429,521 \$431,851	 Asphalt repaving Parkway concrete Pavement seal coat
2025 (Prelim)	\$801,915	 2024: 3 cul-de-sacs (82,586 SF) 2025: 9 cul-de-sacs (105,264 SF)
Increase/(Decrease) % Change	\$370,064 86%	
		and deferral of 2 cul-de-sacs from 2024. s and paving; 12 cul-de-sacs planned for seal coat in 2025. 25



2025 Reserves: Waste L	ine Remediation
2023 Actual \$935,789	 Epoxy lining for interior and exterior waste lines
2024 Adopted \$1,500,000	 Program started in 2006
2025 (Prelim) \$1,500,000	 385 out of 1,405 buildings completed as of 2023
Increase/(Decrease) \$0	 7 GV buildings planned for 2024
% Change	 7 GV buildings planned for 2025
Proposed funding based on competitively b	id contract prices.



2025 Reserve	es: Plumb	ing Replacement
2023 Actual	\$0	 Contract services for pressure regulator valve installations
2024 Adopted	\$200,000	 Approximately 650 buildings are candidates for installations
2025 (Prelim)	\$200,000	candidates for installations
Increase/(Decrease)	\$0	
% Change		
Proposed funding based or	100 valve installat	ions annually.



2025 Reserves: Laundry Countertop and Floor Replacement


2023 Actual	\$13,411
2024 Adopted	\$59,173
2025 (Prelim)	\$42,414
Increase/(Decrease)	(\$16,758)
% Change	(28%)

• 243 laundry rooms in the 3-story buildings

THIRD LAGUNA HILLS

- 44 stand-alone laundry rooms
- 419 countertops
- Replace sheet vinyl flooring with epoxy coating
- Countertop replacements
- Contract services for asbestos abatement \$30,000

Proposed decrease based on historical expenditure trend for laundry room countertops.



Description	2023 Actual	2024 Budget	2025 Budget	Increase / (Decrease)	% Change
Building Structures	\$2,403,923	\$2,300,426	\$2,486,143	\$185,717	8%
Electrical Systems	\$0	\$30,000	\$62,000	\$32,000	107%
Exterior Lighting	\$12,062	\$12,500	\$12,925	\$425	3%
Fencing	\$75,237	\$79,602	\$70,757	(\$8,844)	(11%)
Garden Villa Mailroom	\$293	\$562	\$577	\$15	3%
Garden Villa Rec Room	\$8,472	\$65 <i>,</i> 393	\$68,109	\$2,716	4%
Gutters	\$67,264	\$126,486	\$203,575	\$77,089	61%
Mailboxes	\$11,811	\$27,582	\$27,640	\$58	0%
Paint Program	\$1,445,812	\$1,613,075	\$1,757,800	\$144,725	9%
Prior-to-Paint Program	\$1,161,592	\$1,222,353	\$1,437,585	\$215,232	18%

2025 Summary of Reserve Expenditures

THIRD LAGUNA HILLS


Description	2023	2024	2025	Increase /	%
	Actual	Budget	Budget	(Decrease)	Change
Paving	\$429,521	\$431,851	\$801,915	\$370,064	86%
Roofs	\$1,477,360	\$1,684,823	\$1,940,618	\$255,795	15%
Waste Line Remediation	\$935,789	\$1,500,000	\$1,500,000	\$0	0%
Copper Water Line Remediation	\$196,116	\$1,000,000	\$1,000,000	\$0	0%
Plumbing Replacement	\$0	\$200,000	\$200,000	\$0	0%
Elevators	\$98,680	\$125,000	\$205,800	\$80,800	65%
Laundry Countertop/Floor	\$13,411	\$59,173	\$42,414	(\$16,758)	(28%)
Laundry Appliances	\$170,745	\$109,593	\$164,499	\$54,907	50%
Total	\$8,508,089	\$10,620,819	\$11,982,357	\$1,361,539	13%


2025 Additional Budget Considerations M&C Committee



The M&C Committee requested the Board of Directors consider including the following budget items for 2025:

- \$100,000 for consultant services to develop a Renewable Energy Plan
- \$35,000 for installation of hand rails at GV building entrances
- \$ 613,000/year to complete the refurbishment of 18 elevators in two years
- \$158,000 to hire part-time consultant Quality Control Inspectors with plumbing, electrical, roofing licenses





Operating: Janitorial Services



Funds various janitorial services for various facilities in Third Mutual

THIRD MUTUAL	FREQUENCY
Two-story buildings (breezeways)	Upon request
Laundry rooms	Every 3 weeks
Laundry restrooms	1x week
Garden Villas	1x week
LH 21 buildings	1x week
Miscellaneous tickets	Weekly
PROGRAMS	•
Carport cleaning	3x year
Water boiler enclosure cleaning	1x year
Trash enclosure cleaning	1x year

Operating:	Janitorial Services		
	2023 Actual	\$899,490	
	2024 Adopted	\$904,120	
	2025 (Prelim)	\$892,757	
	Increase/(Decrease)	(\$11,362)	
	% Increase/(Decrease)	(1%)	-



rating: Concrete Servic	es	THIRD LAGUNA HILLS
Description	Tickets	
Concrete Repair/Replaced	258	
Masonry Work	29	
Concrete Grinding Completed	55	
Paving Misc. Service	25	
		5

Operating	: Concrete Services		THIRD LAGUNA HILLS
	2023 Actual	\$386,373	
	2024 Adopted	\$336,286	
	2025 (Prelim)	\$352,348	
	Increase/(Decrease)	\$16,062	
	% Increase/(Decrease)	5%	

Operating: Gutter Cleaning Service



THIRD LAGUNA HILLS

- Provides for cleaning of building rain gutters to ensure proper function and drainage
- Majority of work is completed during fourth quarter, prior to winter
- Includes funding for an outside vendor to clean gutters of multistory buildings once during fourth quarter
- In-house staff clean gutters of singlestory buildings throughout year on a scheduled and as-requested basis



Operating: Gutter Cleaning Service


Description	Units
Single Story	894
Multi-Story	337
Patio Covers	1,471

Operating	g: Gutter Cleaning Se	ervice	THIRD LAGUNA HILLS
	2023 Actual	\$135,528	
	2024 Adopted	\$207,597	
	2025 (Prelim)	\$200,011	
	Increase/(Decrease)	(\$7,586)	
	% Increase/(Decrease)	(4%)	



Operati	ng: Welding Service		
	2023 Actual	\$98,365	
	2024 Adopted	\$107,821	-
	2025 (Prelim)	\$113,099	
	Increase/(Decrease)	\$5,279	
	% Increase/(Decrease)	5%	





O	perati	ng: Traffic Control		THIRD LAGUNA HILLS
		2023 Actual	\$21,334	
		2024 Adopted	\$18,129	
		2025 (Prelim)	\$18,930	
		Increase/(Decrease)	\$801	
		% Increase/(Decrease)	4%	
				1

2025 Business Plan Third Laguna Hills Mutual

General Services Business Planning Meeting - Reserve Fund May 23, 2024

Reserves: Prior to Paint


Mutual 15-year full exterior paint program includes contingency for railing, stairway metal work, balcony railing and other welding repairs on buildings scheduled for 2025 exterior paint program.


936 will need to address metal issues in about 15% of the buildings in Third



THIRD LAGUNA HILLS

THIRD LAGUNA HILLS





2023 Actual \$64,678 2024 Adopted \$82,343 2025 (Prelim) \$86,279 Increase/(Decrease) \$3,936 % Increase/(Decrease) 5%	Reserves:	Paving/Concrete		THIRD LAGUNA HILLS
2025 (Prelim) \$86,279 Increase/(Decrease) \$3,936		2023 Actual	\$64,678	
Increase/(Decrease) \$3,936		2024 Adopted	\$82,343	
		2025 (Prelim)	\$86,279	
% Increase/(Decrease) 5%		Increase/(Decrease)	\$3,936	
	9	6 Increase/(Decrease)	5%	

